



**Photograph 1 – Cell 12A, Excavation of NAPL impacted materials that extended into the riverbank**



**Photograph 2 – Cell 12A NAPL Excavation**



**Photograph 3 – Cell 12A NAPL**



**Photograph 4 – Cell 12A Backfilling Activities**



**Photograph 5 – Cell 12A Restored**



**Photograph 6 – Temporary Dam Construction**



**Photograph 7 – Temporary Dam Construction**



**Photograph 8 – Installation of the Helical Anchors for the 54-inch Pipe**