



Photo 1. *Dredge discharge pipe staging area north of Timbalier Island*



Photo 3. *Preparing dredge pipe for transport and installation (submerged pipe)*



Photo 2. *Dredge discharge pipe staging area north of Timbalier Island*



Photo 4. *Dredge discharge shore pipe on barge*



Photo 5. Dredging access channel with spud barge-mounted bucket dredge, looking south



Photo 7. View of back dike from within access channel looking southeast



Photo 6. Camp at Sta. 167+00, photo taken from within access channel on bucket dredge barge looking south.



Photo 8. Construction of back dike with marsh buggy excavators progressing westward, looking southwest from within access channel



Photo 9. View of back dike constructed west of access channel looking southwest from within access channel



Photo 11. View of east dike and end of submerged dredge pipe at east end of project looking northwest from the Gulf (before shore pipe installation)



Photo 10. Island end of submerged dredge pipe at east end of project looking northwest from the Gulf (before shore pipe installation)



Photo 12. View of east dike at east end of project looking northwest from the Gulf



Photo 13. *View of shoreline looking west from east end of project*



Photo 15. *East dike at end of project (Sta. 206+00), looking south from back dike*



Photo 14. *View of buoys marking submerged dredge pipe looking southeast from island*



Photo 16. *East dike at end of project (Sta. 206+00), looking southeast from back dike*



Photo 17. East dike at end of project (Sta. 206+00), looking north



Photo 19. East dike at end of project (Sta. 206+00), looking north



Photo 18. East dike at shoreline and end of submerged dredge pipe, looking south



Photo 20. End of submerged dredge pipe at east end of project, looking south



Photo 21. End of submerged dredge pipe at east end of project, looking south



Photo 23. East dike at east end of project, looking north from Sta. 205+00



Photo 22. End of east dike at beach, looking east



Photo 24. View of back dike looking north from beach (appx. Sta. 200+00)



Photo 25. *Dredging access channel with bucket dredge, looking northwest from beach at appx. Sta. 187+00*



Photo 27. *View of camp (at Sta. 167+00), looking west*



Photo 26. *View of access berm at end of access channel, looking northwest*



Photo 28. *Dredging access channel with bucket dredge, looking north from appx. Sta. 170+00*



Photo 29. View of camp at Sta. 167+00 looking south



Photo 31. Construction of back dike at appx. Sta. 125+00 using marsh buggy excavators, looking south from bay



Photo 30. View of cut in island (at Sta. 165+00) looking southwest from Sta. 167+00



Photo 32. Construction of back dike at appx. Sta. 125+00 using marsh buggy excavators, looking west



Photo 33. View of back dike looking east from appx. Sta. 129+00



Photo 35. View of back dike looking east from appx. Sta. 127+00



Photo 34. Construction of back dike at appx. Sta. 125+00 using marsh buggy excavators, looking west



Photo 36. Construction of back dike at appx. Sta. 125+00 using marsh buggy excavators, looking southeast from bay