




- Legend**
- Existing Monitoring Well (Installed by Others)
 - Existing Monitoring Well (Installed by Antea Group (former Delta Consultants))
 - Existing Monitoring Well (Installed by Antea Group (former Delta Consultants in 2009))
 - (88.92) Groundwater Elevation
 - Groundwater Elevation Contour
 - (NM) Not Measured
 - (NLP) No Longer Present
 - Generalized Groundwater Flow Direction
- All Elevations Shown in Feet
 Contour Interval = 0.50 foot
 ** Deep Well Not Used in Contouring



GROUNDWATER ELEVATION
 CONTOUR MAP
 SEPTEMBER 26, 2016

**FORMER MCCANDLESS
 FUELS SITE**

2231 Delsea Drive
 Franklinville, New Jersey


RCC Resource Control Consultants
 10 LIPPINCOTT LA. MT. HOLLY, NJ 08060
 Tel. (856) 273-1009 Fax (856) 273-1012
 1-800-Remed-8

SOURCE: antea group
 20161101_MCCANDLESS

FILE NAME: 18016_EndpointGW

JOB NO.: 18016

DESIGNED: JMM
DETAILED: SGH
CHECKED: JMM
DATE: 5/5/2017
FIGURE: 14A




Legend

- Existing Monitoring Well (Installed by Others)
- Existing Monitoring Well (Installed by Antea Group (former Delta Consultants))
- Existing Monitoring Well (Installed by Antea Group (former Delta Consultants in 2009))

Results reported in ug/L (Micrograms per liter).

PCBs Polychlorinated Biphenyls.
 ND Not Detected.
 D Sample results are obtained from a dilution; the surrogate or matrix spike recoveries reported are calculated from diluted samples.



POST OZONE INJECTION PCB GW RESULT PLOT
 POLYCHLORINATED BIPHENYLS (PCBs)
 SEPTEMBER 28 THROUGH SEPTEMBER 30, 2016

FORMER MCCANDLESS FUELS SITE

2231 Delsea Drive
 Franklinville, New Jersey

10 LIPPINCOTT LA. MT. HOLLY, NJ 08060
 Tel. (856) 273-1009 Fax. (856) 273-1012
 1-866-Remedi-8

DESIGNED:	JMM
DETAILED:	SGH
CHECKED:	JMM
DATE:	5/5/2017
FILE NAME:	18016_EndpointGW
JOB NO.:	18016
FIGURE:	14B

SOURCE:	anteagroup 20161101_MCCANDLESS
---------	-----------------------------------