



Disclaimer

The information in this presentation has been reviewed and approved for public dissemination in accordance with U.S. Environmental Protection Agency (EPA). The views expressed in this presentation are those of the author(s) and do not necessarily represent the views or policies of the Agency. Any mention of trade names or commercial products does not constitute EPA endorsement or recommendation for use.

GI Evaluation in Urban Areas: Strategies and Challenges



This research has been supported by a grant from the U.S. Environmental Protection Agency's Science to Achieve Results (STAR) program.



The goal of monitoring is to evaluate the performance of GI

Stormwater capture

Infiltration

Sustainability / maintenance

Impact (CSO reduction, groundwater mounding, surface ponding, neighborhood)



What do we monitor?

- Rainfall
- Topography
- Inflows
- Outflows
- Storage
- Infiltration rates
- Water table
- Soil properties
- Plant health



What are the monitoring costs?

- Rain gauges \$
- Water level loggers \$
- Communication \$ to \$\$
- Soil moisture loggers \$\$
- Flow meters \$\$
- Calibration \$ to \$\$
- Construction \$\$ to \$\$\$
- Drilling \$\$\$
- LiDAR (airborne or surface) \$\$\$
- Geophysics \$\$ to \$\$\$
- Infiltration surveys \$
- Compaction surveys \$
- Maintenance \$\$



- Technical support \$\$\$
- \$ 100's \$\$ 1000's \$\$\$ 10000's

What are the monitoring costs?

- Rain gauges \$
- Water level loggers \$
- Communication \$ to \$\$
- Soil moisture loggers \$\$
- Flow meters \$\$
- Calibration \$ to \$\$
- Construction \$\$ to \$\$\$
- Drilling \$\$\$
- LiDAR (airborne or surface) \$\$\$
- Geophysics \$\$ to \$\$\$
- Infiltration surveys \$
- Compaction surveys \$
- Maintenance \$\$




- Technical support \$\$\$
- \$ 100's \$\$ 1000's \$\$\$ 10000's

Monitoring presents challenges

- Equipment failure
- Power
- Communication
- Cost
- Reliability
- Seasonal variation
- Heterogeneity

- And more...



Data gaps



All-weather monitoring

Some challenges are unique to urban settings

- Permits
- Infrastructure**
- Community acceptance
- Equipment disturbance
- By pass
- Clogging
- Heterogeneity



Some challenges are unique to urban settings

- Permits
- Infrastructure
- Community acceptance
- Equipment disturbance
- By pass
- Clogging
- Heterogeneity**



If It Doesn't Get In, We Can't Measure It



Surface flow bypassing trench drain



Effects of post-construction enhancements



Inflow backing up due to debris and clogging

What are we learning from monitoring?

- ❑ Comparison of design strategies



- ❑ Modeling input




- ❑ Old versus new design




- ❑ Oversizing




Comparison of upflow and downflow design



Downflow design treats more water than expected



Upflow design creates stormwater bypass




Wakefield raingarden instrumentation

- Tensiometers (red dots)
- Wells and water level loggers (yellow dots)




Tensiometer data used to calibrate model


Wakefield Park TS1 tensiometer data
Urban grass/soil outside of basin



Wakefield Park TS1 tensiometer data
Infiltration basin




Oversized trench keeps stormwater from pits



Stormwater tree trench


Old versus new stormwater control



Infiltration trench: 82 m by 2.4 m


□ The trench responded only to big storms

□ The old pipe design responded to every storm




Monitoring helps assess what happens when GI isn't working



- Groundwater mounding
- Bypassing
- No storage
- Season variations
- Infiltration difficult to predict



Infiltration basin received water from roof of new science building




Stormwater mounding should not be within 0.6 m of trench




Storm with and without mounding in tree trench



UNH A-Lot Philly Tree Trench Hydrologic Performance
Individual Storm 9/29/15 : Total Rain = 2.51"



UNH A-Lot Philly Tree Trench Hydrologic Performance
Individual Storm 8/11/15 : Total Rain = 0.64"





Seasonality affects results




- Event rainfall depth is related to peak water level, but only Apr-Sept
- Long term monitoring is needed



Bypassing means storm isn't fully captured



Ground-based LiDAR may determine capture areas better



Trim the trees & delineate capture areas




Football field basin designed to capture street overflow



Football field basin designed to capture street overflow, but doesn't



Blue roof was not storing water




Retrofit with \$5 supplies from hardware store

- ❑ Reduce size of overflow holes on one roof
- ❑ Leave the other roof as original size



Success! Now need to watch out for clogging





Can geophysics help?

- ❑ Finding infrastructure: yes, but it adds to the cost
- ❑ Monitoring infiltration: mixed results



GPR did not predict infiltration rate in urban soil

Infiltration Rate v GPR Reflectivity



Electrical resistivity was tried next





- If it doesn't rain, use a sprinkler



- EM profiler survey in rows

Results are promising using an inversion model to calculate infiltration



$$\sigma_{dry} = 9.4 \text{ mS}$$

$$\sigma_{wet} = 15.0 \text{ mS}$$

Thickness = 1.0 m

Velocity = 0.37 m/hour

Long term monitoring should include

Community driven

- Inspection & maintenance
- Vegetation surveys



CHECKLIST FOR INSPECTION OF BIORETENTION SYSTEM / TREE FILTERS		
Location:		
Inspector:		
Date:		
Time:		
Site Conditions:		
Days Since Last Rain Event:		
Inspection Items	Satisfactory (S) or Unsatisfactory (U)	Comments/Corrective Action
1. Initial Inspection After Planting		
Plants are stable, roots not exposed	S U	
Surface is at design level, no evidence of preferential flow/shoving	S U	
Inlet and outlet/bypass are functional	S U	
2. Debris Cleanup (1 time/year minimum, Spring/Fall)		
Litter, leaves, and dead vegetation removed from the system	S U	
Prune/mow vegetation	S U	
3. Standing Water (1 time/year and/or after large storm events)		
No evidence of standing water after 24-48 hours since rainfall	S U	
4. Vegetation Condition and Coverage		
Vegetation condition good with good coverage (typically > 75%)	S U	
5. Other Issues		
Note any additional issues not previously covered.	S U	
Corrective Action Needed		Due Date
1.		
2.		
3.		
Inspector Signature		Date

Some maintenance requires technical support (P W D program)



Long term monitoring should include

Performance effectiveness

- Sensor installation
- Solar panels
- Routine data collection & synthesis
- Updates on land use



Low cost solar panel data loggers

GI Evaluation in Urban Areas

We've come a long way,
but questions remain



This research has been supported by a grant from the U.S. Environmental Protection Agency's Science to Achieve Results (STAR) program.

FUTURE MONITORING ISSUES

- ❑ What is the scalability and transferability of our approaches?
- ❑ Effectiveness is not constant. How do we account for changing variables such as plants, ET, seasons, land use?
- ❑ How can our results be used to improve designs from a maintenance perspective? Leads to greater acceptability in GI installation.
- ❑ How are monitoring for operation, maintenance and design linked?

QUESTIONS continued

- How can we use monitoring information to inform future design?
- How can we use monitoring to better calibrate models?
- What are key characterization strategies to recommend?
- Do we have a “minimum effective” monitoring strategy?
- How would that vary from site to site?
- What is a good way to convey the lessons learned to practitioners?