



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY**  
 REGION 5  
 77 WEST JACKSON BOULEVARD  
 CHICAGO, IL 60604-3590

| Inspection Photo Log            |                  |  |                                 |
|---------------------------------|------------------|--|---------------------------------|
| Inspection Compliance Rule:     | AHERA            | Inspection Date:                         | 4/4/24                          |
| Facility Name:                  | Warren           | Facility Address, City, State, Zip Code: | 5003 261 Elm Rd Warren OH 44483 |
| Inspector-Photographer Name(s): | Brandon Brewster | Number of Photographs Taken:             | 75 Photos                       |
| Camera Used:                    | 842376           | Digital Recording Media:                 | SD Card                         |
| Notes:                          |                  |  |                                 |

| Sample No. | Digital File No. | Time Taken | Location                   | Direction | Description of Digital Image |
|------------|------------------|------------|----------------------------|-----------|------------------------------|
| 1          | 100-0540 .JPG    | 10:02am    | Conference/teachers lounge | —         | test photo                   |
| 2          | 0541 .JPG        | 10:04am    | Gymnasium                  | E         | Gymnasium from stage         |
| 3          | 0542 .JPG        | 10:05am    | Stage in gym Area          | S         | Piping south wall of stage   |
| 4          | 0543 .JPG        | 10:06am    | "                          | N         | Piping North wall of stage   |

Activities  
Bottom  
Bottom of  
page 7/8

|    |      |      |          |                                    |               |   |
|----|------|------|----------|------------------------------------|---------------|---|
| 5  | 0544 | .JPG | 10:06 am | Gym Stage Area<br>North Stairwell  | N             | Paint crumbling on ceiling<br>and floor tiles                   |
| 6  | 0545 | .JPG | 10:09 am | Gym, Stage Area<br>South Stairwell | S             | Paint crumbling ceiling<br>and walls                            |
| 7  | 0546 | .JPG | 10:14 am | Gym Area<br>South East Storage     | SE            | South East storage closet<br>Paint Debris New and old<br>Piping |
| 8  | 0547 | .JPG | 10:14 am | "                                  | "             | Paint crumbling ceiling + walls<br>new piping + old piping      |
| 9  | 0548 | .JPG | 10:14 am | "                                  | "             | Debris on floor<br>paint + other                                |
| 10 | 0549 | .JPG | 10:15 am | Gym risers                         | South<br>East | SE ceiling tile replacement<br>Crumbling flaking paint          |
| 11 | 0600 | .JPG | 10:19 am | Gym Area NW<br>closet "            | NW<br>"       | Photo from door shows<br>Damage, collapsed ceiling tile + Paint |
| 12 | 0601 | .JPG | 10:20 am | "                                  | "             | Floor Debris, ceiling tile<br>and Paint                         |
| 13 | 0602 | .JPG | 10:20 am | "                                  | "             | close up of ceiling collapsed<br>Area, + flaking paint          |
| 14 | 0603 | .JPG | 10:20 am | "                                  | "             | Debris in closet general<br>ceiling tile + flaking paint        |
| 15 | 0604 | .JPG | 10:25 am | SW Storage room<br>/ Kitchen       | SW            | Paint debris in Bucket  |
| 16 | 0605 | .JPG | 10:25 am | "                                  | "             | Paint Brush +<br>Debris in trash                                |
|    |      | .JPG |          |                                    |               |   |

|    |      |      |         |   |    |   |
|----|------|------|---------|---|----|---|
| 17 | 0606 | .JPG | 10:25am | SW Storage room / Kitchen                         | SW | Paint + cleaning supplies                                       |
| 18 | 0607 | .JPG | 10:26am | "   | "  | Roof leak + Damage  |
| 19 | 0608 | .JPG | 10:26am | "   | "  | "   |
| 20 | 0609 | .JPG | 10:30am | "   | "  | Full room photo   |
| 21 | 0610 | .JPG | 10:31am | SW Stairwell<br>Piping to water meter room        | SW | Piping to water meter room<br>significant paint Debris on floor |
| 22 | 0611 | .JPG | 10:31am | SW stairwell<br>water meter room                  | SW | significant Paint<br>Debris                                     |
| 23 | 0612 | .JPG | 10:35am | Abandoned bathroom<br>storage                     |    | Insulated 4in line, 2in<br>lines                                |
| 24 | 0613 | .JPG | 10:35am | " Facing North<br>Southern section of lower level |    | Bathroom + Paint<br>Debris "                                    |
| 25 | 0614 | .JPG | 10:35am | "   | "  | "   |
| 26 | 0615 | .JPG | 10:36am | <del>Cabeteria</del><br><del>Facing West</del>    | "  | close up of Debris  |
| 27 | 0616 | .JPG | 10:39am | Cabeteria<br>Facing West                          |    | Full Cabeteria<br>photo   |



|    |      |      |          |                              |             |  |
|----|------|------|----------|------------------------------|-------------|--|
| 28 | 0617 | .JPG | 10:42 am | Boiler Room                  | Facing<br>N | general photo  |
| 29 | 0618 | .JPG | 10:43 am | "                            |             | Gasket Debris<br>Suspect ACM                             |
| 30 | 0619 | .JPG | 10:43 am | "                            |             | old Gasket   |
| 31 | 0620 | .JPG | 10:44 am | "<br>Against<br>Western Wall | "           | above photo's Gasket<br>" Edges                          |
| 32 | 0621 | .JPG | 10:44 am | "                            | "           | "  |
| 33 | 0622 | .JPG | 10:46 am | Boiler room<br>main room     | Facing<br>N | Full room photo<br>Paint Debris on ground NE             |
| 34 | 0623 | .JPG | 10:46 am | "                            | "           | Old Boiler Gasket removed                                |
| 35 | 0624 | .JPG | 10:47 am | "                            | "           | Pipe runs  |
| 36 | 0625 | .JPG | 10:48 am | Boiler room                  | "           | Pipe runs to the right<br>that are cut off in photo 0617 |
| 37 | 0626 | .JPG | 10:52 am | Cafe Basement                |             | Maps of lower level                                      |
| 38 | 0627 | .JPG | 10:54 am | low-level<br>hallway         | Facing<br>S | Full hall way<br>trazo flooring & Drop<br>Ceiling tile   |

|    |      |      |          |   |             |   |
|----|------|------|----------|---|-------------|---|
| 39 | 0628 | .JPG | 10:56 am | N storage / Crystal clear / Book storage room | N           | Crystal clear to the right<br>Book Kids workspace left floor tile     |
| 40 | 0629 | .JPG | 10:57 am | Book storage<br>Kids workspace                | N           | pipings, construction?<br>Kids work space                             |
| 41 | 0630 | .JPG | 10:57 am | Crystal clear<br>Waste storage                | N           | Celloglytix with ribbon<br>on top                                     |
| 42 | 0631 | .JPG | 10:57 am | Crystal clear<br>Storage Area                 | N           | glue pucks Steam lines  |
| 43 | 0632 | .JPG | 10:57 am | "   | "           | "   |
| 44 | 0634 | .JPG | 11:02 am | "<br>Facing                                   | S           | Steam line + glue<br>pucks  |
| 45 | 0635 | .JPG | 11:03 am | "<br>South portion of<br>above photo          |             | glue pucks<br>Close up  |
| 46 | 0636 | .JPG | 11:05 am | Room 109                                      |             | 1st floor floor plan of 109   |
| 47 | 0637 | .JPG | 11:06 am | Room 109                                      | Facing<br>E | Room 109 ceiling + floor<br>tile                                      |
| 48 | 0638 | .JPG | 11:08 am | Room 107                                      | SW<br>wall  | Base Board w/ possible mastic<br>detached / crumbling from wall       |
| 49 | 0639 | .JPG | 11:11 am | 1st Fl Hallway<br>west end                    |             | <del>Full hallway</del><br>Full hallway<br>Floor tile<br>in dark area |

looking E

terzo in  
1st  
portion

|    |                         |      |          |   |                          |  |
|----|-------------------------|------|----------|---|--------------------------|--|
|    | 0639                    |      |          |   |                          |  |
| 50 | <del>0639</del><br>0640 | .JPG | 11:14 am | 2nd fl hallway<br>East end looking west |                          | Full hallway<br>photo  |
| 51 | 0646                    | .JPG | 11:16 am | technology/<br>server room              | looking<br>East          | Damage ceiling and<br>room paint                                 |
| 52 | 0641                    | .JPG | 11:17 am | "                                       | North<br>west            | Paint debris crown<br>floor perimeter                            |
| 53 | 0642                    | .JPG | 11:19 am | floor plan<br>2nd & 100                 |                          |  |
| 54 | 0643                    | .JPG | 11:21 am | womens restroom<br>2nd floor            | west<br>end looking<br>N | Pipes against North<br>wall                                      |
| 55 | 0644                    | .JPG | 11:21 am | "                                       | "                        | zoom on duct tape<br>patch on potential aerosol                  |
| 56 | 0645                    | .JPG | 11:24 am | 3rd fl SW<br>Wrestroom closet           |                          | peeling ceiling paint  |
| 57 | 0646                    | .JPG | 11:24 am | "                                       |                          | pulverized dust material<br>in sink                              |
| 58 | 0647                    | .JPG | 11:26 am | 3rd floor hallway<br>west end           | looking<br>East          | two types of floor tile  |
| 59 | 0648                    | .JPG | 11:28 am | 302 old East<br>labroom end             | Facing<br>west           | Full photo, Lab tables<br>Plaster ceiling/walls, debris on floor |
| 60 | 0649                    | .JPG | 11:29 am | 302 "                                   | NE                       | Lab tables   |



WSE

|    |      |      |          |   |                   |   |
|----|------|------|----------|---|-------------------|---|
| 61 | 0650 | .JPG | 11:29 am | 302   | looking E         | Plaster walls/ceiling<br>11 Crumbling                     |
| 62 | 0651 | .JPG | 11:29 am | 302   | N wall            | Debris from ceiling                                       |
| 63 | 0652 | .JPG | 11:30 am | 302   | N wall<br>ceiling | Zoom in on damage<br>seen in 0650                         |
| 64 | 0653 | .JPG | 11:30 am | 302   | Against<br>E wall | Fire blanket / Black<br>board                             |
| 65 | 0654 | .JPG | 11:31 am | 301 door<br>marked Library                  | South<br>wall     | Peeling paint   |
| 66 | 0655 | .JPG | 11:37 am | 306   |                   | Crumbling peeling plaster<br>4 ceiling                    |
| 67 | 0656 | .JPG | 11:37 am | 306   | 4                 | 4 ceiling<br>along North wall of<br>Class room            |
| 68 | 0657 | .JPG | 11:39 am | East End 3rd<br>Floor Mens Room             | looking<br>East   | ceiling peeling   |
| 69 | 0658 | .JPG | 11:40 am | East End 3rd<br>Floor Womens / staff & bath | looking<br>West   | hole in ceiling plaster                                   |
| 70 | 0659 | .JPG | 11:43 am | 304 2nd room                                | looking<br>West   | Full room photo Crumbling<br>ceiling plaster              |
| 71 | 0660 | .JPG | 11:43 am | 11  | South<br>Wall     | Crumbling flaking paint / plaster<br>wall Debris on floor |

|    |      |      |         |                            |                         |  |
|----|------|------|---------|----------------------------|-------------------------|--|
|    |      |      |         |                            |                         |  |
| 72 | 0661 | .JPG | 11:43am | 304 2nd room               | South wall<br>west side | Crumbing + flaking paint<br>Crack in wall      |
| 73 | 0662 | .JPG | 11:44am | 11                         | West wall               | Base board possible<br>exposed mastic adhesive |
| 74 | 0663 | .JPG | 11:45am | 304 2nd room<br>doorway    | Looking South           | Possible exposed mastic<br>missing floor tile  |
| 75 | 0664 | .JPG | 12:06pm | STEAM Academy<br>of Warren | South side              | School photo                                   |
|    |      | .JPG |         |                            |                         |  |
|    |      | .JPG |         |                            |                         |  |
|    |      | .JPG |         |                            |                         |  |
|    |      | .JPG |         |                            |                         |  |
|    |      | .JPG |         |                            |                         |  |
|    |      | .JPG |         |                            |                         |  |
|    |      | .JPG |         |                            |                         |  |
|    |      | .JPG |         |                            |                         |  |