Photograph 1 - Silver Lake Extension Construction Activities; outfall blocked and discharge pumped around Cell 5A

Photograph 2 – Cell 5A with Silver Lake Outfall Structure

Photograph 3 - Cell 8 Bank Excavation Activities

Photograph 4 - Cell 8 Restored

Photograph 5 - Cell 8 Restored with Aquatic Habitat Enhancement Structures

Photograph 6 - Cell 8A Post Excavation Elevation Survey

Photograph 7 - Cell 9 Completed Excavation

Photograph 8 - Cell 9 Backfilling Activities