Photograph 1 – Fusion Welding of 54-inch Gravity Bypass Pipe

Photograph 2 – 54-inch Gravity Bypass Pipe

Photograph 3 – Cell 11A, Permanent Retaining Wall and Riverbed/Riverbank Backfilling Activities

Photograph 4 – Cell 11A, Compacting Common Fill Filter Layer on the Riverbank

Photograph 5 – Cell 11A Restored

Photograph 6 – Tree Planting Activities

Photograph 7 – Installation of the Center Column of the Temporary Dam

Photograph 8 – Overview of Completed Restoration