BACK TO DIGITAL INDEX

ATTACHMENT 23

Surface Geologic Map



SAN JOAQUIN ENERGY CONSULTANTS, INC.
1400 Easton Drive, Suite 133, Bakersfield, CA 93309

Attachment 23

Surface Geologic Map
Hilmar Cheese Company
Merced County, California

Source: Rogers, 1977 Date: 9/04