RAYMARK
3.06
18025

APPENDIX C

ANALYTICAL DATA

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	001		002		003		004		005		006		007		008		009		A001	
Sample Location	001		002		003		004		005		006		007		008		009		A001	
Date Sampled																				
QC Identifier	None		None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																				
Aroclor-1016	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
Aroclor-1221	67	U	67	U	67	U	67	U	67	U	67	U	67	U	67	U	67	U		NA
Aroclor-1232	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
Aroclor-1242	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
Aroclor-1248	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
Aroclor-1254	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
Aroclor-1260	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
Aroclor-1262	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U	33	U		NA
PCB Screening Analysis (UG/KG)																				
Aroclor-1268	10000	U	10000	U	7000		10000	U	10000	U	10000	U	10000	U	10000	U	10000	U		NA
Aroclor, Total	10000	U	10000	U	7000		10000	U	10000	U	10000	U	10000	U	10000	U	10000	U		NA
TAL Metal Analysis (MG/KG)																				
Arsenic	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U		NA
Barium	40.0	U	40.0	U	40.0	U	40.0	U	40.0	U	40.0	U	40.0	U	40.0	U	40.0	U		NA
Beryllium	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U		NA
Cadmium	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U		NA
Chromium	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U		NA
Cobalt	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U		NA
Copper	5.0	U	5.0	U	5.0	U	5.0	U	5.0	U	5.0	U	5.0	U	5.0	U	5.0	U		NA
Lead	300		350		160		170		220		250		350		180		950			NA
Manganese	3.0	U	3.0	U	3.0	U	3.0	U	3.0	U	3.0	U	3.0	U	3.0	U	3.0	U		NA
Nickel	8.0	U	8.0	U	8.0	U	8.0	U	8.0	U	8.0	U	8.0	U	8.0	U	8.0	U		NA
Vanadium	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U		NA
Zinc	4.0	U	4.0	U	4.0	U	4.0	U	4.0	U	4.0	U	4.0	U	4.0	U	4.0	U		NA
Metal Screening by XRF Analysis (MG/KG)																				
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																				
Asbestos	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	40	

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	A002		A003		A013		A014		A015		A016		A017		A018		A019		A020		A021	
Sample Location	A002		A003		A013		A014		A015		A016		A017		A018		A019		A020		A021	
Date Sampled																						
QC Identifier	None		None		None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																						
Aroclor-1016		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1242		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1248		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1254		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1260		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1262		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
PCB Screening Analysis (UG/KG)																						
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																						
Arsenic		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Barium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Chromium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Copper		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Manganese		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Nickel		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Zinc		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)																						
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																						
Asbestos	45		20		0.1	U	0.1	U	0.1	U	0.1	U	0.9		0.9		0.1	U	0.1	U	0.1	U

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	A022		A023		A024		A025		A026		A027		A028		A029		A030		A031		A032	
Sample Location	A022		A023		A024		A025		A026		A027		A028		A029		A030		A031		A032	
Date Sampled																						
QC Identifier	None		None		None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																						
Aroclor-1016		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1242		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1248		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1254		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1260		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1262		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
PCB Screening Analysis (UG/KG)																						
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																						
Arsenic		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Barium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Chromium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Copper		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Manganese		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Nickel		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Zinc		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)																						
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																						
Asbestos	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.1	U	0.9		0.1	U	0.1	U

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	A033		A034		A035		010		BF001		BF002		BF003		BF004		BF005	
Sample Location	A033		A034		A035		010		BF001		BF002		BF003		BF004		BF005	
Date Sampled																		
QC Identifier	None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																		
Aroclor-1016		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1242		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1248		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1254		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1260		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1262		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA
PCB Screening Analysis (UG/KG)																		
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																		
Arsenic		NA		NA		NA	2.0	U		NA		NA		NA		NA		NA
Barium		NA		NA		NA	40.0	U		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA	1.0	U		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA	1.0	U		NA		NA		NA		NA		NA
Chromium		NA		NA		NA	2.0	U		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA	10.0	U		NA		NA		NA		NA		NA
Copper		NA		NA		NA	5.0	U		NA		NA		NA		NA		NA
Lead		NA		NA		NA	370			NA		NA		NA		NA		NA
Manganese		NA		NA		NA	3.0	U		NA		NA		NA		NA		NA
Nickel		NA		NA		NA	8.0	U		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA	10.0	U		NA		NA		NA		NA		NA
Zinc		NA		NA		NA	4.0	U		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)																		
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																		
Asbestos	0.9		0.9		0.1	U	0.1	U	2		0.9		0.9		0.1	U	0.9	

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF006		BF006-D		BF006-MAX		BF007		BF008		BF009		BF010	
Sample Location	BF006		BF006		BF006		BF007		BF008		BF009		BF010	
Date Sampled														
QC Identifier	Field Dup. BF006		Field Dup. BF006		Field Dup. BF006		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)														
Aroclor-1016	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1221	67	U	67	U	67	U		NA		NA		NA		NA
Aroclor-1232	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1242	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1248	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1254	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1260	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1262	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1268	1000	U		NA	1000	U		NA		NA		NA		NA
Aroclor, Total	33	U	33	U	33	U		NA		NA		NA		NA
PCB Screening Analysis (UG/KG)														
Aroclor-1268		NA	18000		18000			NA		NA		NA		NA
Aroclor, Total		NA	18000		18000			NA		NA		NA		NA
TAL Metal Analysis (MG/KG)														
Arsenic	12.0		27.0		27.0			NA		NA		NA		NA
Barium	70.0		2370		2370			NA		NA		NA		NA
Beryllium	1.0	U	1.0	U	1.0	U		NA		NA		NA		NA
Cadmium	1.0	U	1.0	U	1.0	U		NA		NA		NA		NA
Chromium	17.0		119		119			NA		NA		NA		NA
Cobalt	7.0		25.0		25.0			NA		NA		NA		NA
Copper	82.0		4900		4900			NA		NA		NA		NA
Lead	212		8270		8270			NA		NA		NA		NA
Manganese	254		350		350			NA		NA		NA		NA
Nickel	16.0		351		351			NA		NA		NA		NA
Vanadium	35.0		37.0		37.0			NA		NA		NA		NA
Zinc	183		3410		3410			NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)														
Lead		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)														
Asbestos	0.9			NA	0.9		5		2		0.9		0.9	

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF011		BF012		BF013		BF014		BF015		BF016		BF017		BF018		BF019		BF020	
Sample Location	BF011		BF012		BF013		BF014		BF015		BF016		BF017		BF018		BF019		BF020	
Date Sampled																				
QC Identifier	None		None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																				
Aroclor-1016	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1221	67	U		NA		NA		NA		NA		NA		NA		NA	67	U		NA
Aroclor-1232	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1242	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1248	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1254	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1260	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1262	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1268	1000	U		NA		NA		NA		NA		NA		NA		NA	1000	U		NA
Aroclor, Total	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
PCB Screening Analysis (UG/KG)																				
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																				
Arsenic		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Barium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Chromium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Copper		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Manganese		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Nickel		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Zinc		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)																				
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																				
Asbestos	0.9		0.1	U	0.1	U	0.1	U	0.9		0.1	U	0.1	U	0.9		0.9		0.9	

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF021		BF022		BF023		BF024		BF025		BF026		BF027		BF028		BF029		BF030	
Sample Location	BF021		BF022		BF023		BF024		BF025		BF026		BF027		BF028		BF029		BF030	
Date Sampled																				
QC Identifier	None		None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																				
Aroclor-1016	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1221	67	U		NA		NA		NA		NA		NA		NA		NA	67	U		NA
Aroclor-1232	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1242	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1248	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1254	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1260	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1262	33	U		NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor-1268	35000			NA		NA		NA		NA		NA		NA		NA	33	U		NA
Aroclor, Total	35149			NA		NA		NA		NA		NA		NA		NA	33	U		NA
PCB Screening Analysis (UG/KG)																				
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																				
Arsenic	11.0			NA		NA		NA		NA		NA		NA		NA	2.0	U		NA
Barium	2755			NA		NA		NA		NA		NA		NA		NA	40.0	U		NA
Beryllium	1.0	U		NA		NA		NA		NA		NA		NA		NA	1.0	U		NA
Cadmium	1.0	U		NA		NA		NA		NA		NA		NA		NA	1.0	U		NA
Chromium	24.0			NA		NA		NA		NA		NA		NA		NA	2.0	U		NA
Cobalt	8.0			NA		NA		NA		NA		NA		NA		NA	10.0	U		NA
Copper	4300			NA		NA		NA		NA		NA		NA		NA	5.0	U		NA
Lead	3490			NA		NA		NA		NA		NA		NA		NA	250			NA
Manganese	249			NA		NA		NA		NA		NA		NA		NA	3.0	U		NA
Nickel	58.0			NA		NA		NA		NA		NA		NA		NA	8.0	U		NA
Vanadium	22.0			NA		NA		NA		NA		NA		NA		NA	10.0	U		NA
Zinc	486			NA		NA		NA		NA		NA		NA		NA	4.0	U		NA
Metal Screening by XRF Analysis (MG/KG)																				
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																				
Asbestos		NA	0.9		0.9		8		20		6		0.9		40		0.9		0.1	U

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF031		BF032		BF033		BF034		BF035		BF036		BF037		BF038		BF039		BF040	
Sample Location	BF031		BF032		BF033		BF034		BF035		BF036		BF037		BF038		BF039		BF040	
Date Sampled																				
QC Identifier	None		None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																				
Aroclor-1016	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1221	67	U	67	U	67	U	67	U	67	U	67	U		NA		NA		NA		NA
Aroclor-1232	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1242	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1248	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1254	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1260	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1262	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor-1268	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
Aroclor, Total	33	U	33	U	33	U	33	U	33	U	33	U		NA		NA		NA		NA
PCB Screening Analysis (UG/KG)																				
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																				
Arsenic	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U		NA		NA		NA		NA
Barium	40.0	U	40.0	U	40.0	U	40.0	U	40.0	U	40.0	U		NA		NA		NA		NA
Beryllium	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U		NA		NA		NA		NA
Cadmium	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U		NA		NA		NA		NA
Chromium	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U	2.0	U		NA		NA		NA		NA
Cobalt	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U		NA		NA		NA		NA
Copper	5.0	U	5.0	U	5.0	U	5.0	U	5.0	U	5.0	U		NA		NA		NA		NA
Lead	500		250		280		450		350		300			NA		NA		NA		NA
Manganese	3.0	U	3.0	U	3.0	U	3.0	U	3.0	U	3.0	U		NA		NA		NA		NA
Nickel	8.0	U	8.0	U	8.0	U	8.0	U	8.0	U	8.0	U		NA		NA		NA		NA
Vanadium	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U	10.0	U		NA		NA		NA		NA
Zinc	4.0	U	4.0	U	4.0	U	4.0	U	4.0	U	4.0	U		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)																				
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																				
Asbestos	2		0.9		0.9		0.9		0.9		0.9		0.9		0.9		0.9		0.9	

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF041		BF042		BF043		BF044		BF045		BF046		BF047		BF048		BF049		BF050	
Sample Location	BF041		BF042		BF043		BF044		BF045		BF046		BF047		BF048		BF049		BF050	
Date Sampled																				
QC Identifier	None		None		None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																				
Aroclor-1016		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1242		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1248		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1254		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1260		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1262		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
PCB Screening Analysis (UG/KG)																				
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																				
Arsenic		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Barium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Chromium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Copper		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Manganese		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Nickel		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Zinc		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)																				
Lead		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA
Asbestos Analysis (%)																				
Asbestos	0.9		0.9		0.9		3		2		0.9		0.1	U	0.9		0.9		4	

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF051		BF052		BF001 (1')		BF001 (6")		BF002 (1')		BF002 (6")		BF023A		BF024A	
Sample Location	BF051		BF052		BF001		BF001		BF002		BF002		BF023A		BF024A	
Date Sampled																
QC Identifier	None		None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)																
Aroclor-1016		NA		NA		NA		NA		NA		NA	33	U	33	U
Aroclor-1221		NA		NA		NA		NA		NA		NA	67	U	67	U
Aroclor-1232		NA		NA		NA		NA		NA		NA	33	U	33	U
Aroclor-1242		NA		NA	2000	UF	2000	UF	2000	UF	2000	UF	33	U	33	U
Aroclor-1248		NA		NA	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1254		NA		NA	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1260		NA		NA	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1262		NA		NA	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1268		NA		NA	11000	F	6000	F	2000	UF	2000	UF	33	U	33	U
Aroclor, Total		NA		NA	12066		7066		33	U	33	U	33	U	33	U
PCB Screening Analysis (UG/KG)																
Aroclor-1268		NA		NA		NA		NA		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)																
Arsenic		NA		NA		NA		NA		NA		NA	5.0		6.0	
Barium		NA		NA		NA		NA		NA		NA	95.0		78.0	
Beryllium		NA		NA		NA		NA		NA		NA	1.0	U	1.0	U
Cadmium		NA		NA		NA		NA		NA		NA	1.0	U	1.0	U
Chromium		NA		NA		NA		NA		NA		NA	17.0		14.0	
Cobalt		NA		NA		NA		NA		NA		NA	6.0		5.0	
Copper		NA		NA		NA		NA		NA		NA	11.0		9.0	
Lead		NA		NA		NA		NA		NA		NA	23.0		20.0	
Manganese		NA		NA		NA		NA		NA		NA	560		558	
Nickel		NA		NA		NA		NA		NA		NA	9.0		9.0	
Vanadium		NA		NA		NA		NA		NA		NA	23.0		26.0	
Zinc		NA		NA		NA		NA		NA		NA	49.0		42.0	
Metal Screening by XRF Analysis (MG/KG)																
Lead		NA		NA	1750		770		230		415			NA		NA
Asbestos Analysis (%)																
Asbestos	0.9		0.1	U		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF003 (1')		BF003 (6")		BF037A		BF004 (1')	
Sample Location	BF003		BF003		BF037A		BF004	
Date Sampled								
QC Identifier	None		None		None		None	
Matrix	Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)								
Aroclor-1016		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA
Aroclor-1242	2000	UF	2000	UF		NA	2000	UF
Aroclor-1248	33	U	33	U		NA	33	U
Aroclor-1254	33	U	33	U		NA	33	U
Aroclor-1260	33	U	33	U		NA	33	U
Aroclor-1262	33	U	33	U		NA	33	U
Aroclor-1268	2000	UF	2000	UF		NA	2000	UF
Aroclor, Total	33	U	33	U		NA	33	U
PCB Screening Analysis (UG/KG)								
Aroclor-1268		NA		NA		NA		NA
Aroclor, Total		NA		NA		NA		NA
TAL Metal Analysis (MG/KG)								
Arsenic		NA		NA		NA		NA
Barium		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA
Chromium		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA
Copper		NA		NA		NA		NA
Lead		NA		NA		NA		NA
Manganese		NA		NA		NA		NA
Nickel		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA
Zinc		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)								
Lead	200		350			NA	340	
Asbestos Analysis (%)								
Asbestos		NA		NA	15			NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF004 (6")		BF005 (1')		BF005 (6")		BF006 (1')		BF006 (6")		BF007 (6")		BF007 (1.5')	
Sample Location	BF004		BF005		BF005		BF006		BF006		BF007		BF007	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Analysis (UG/KG)														
Chloromethane		NA		NA		NA		NA		NA		NA		NA
Bromomethane		NA		NA		NA		NA		NA		NA		NA
Vinyl Chloride		NA		NA		NA		NA		NA		NA		NA
Chloroethane		NA		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA		NA
Acetone		NA		NA		NA		NA		NA		NA		NA
Carbon Disulfide		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA		NA
Chloroform		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
2-Butanone		NA		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Carbon Tetrachloride		NA		NA		NA		NA		NA		NA		NA
Bromodichloromethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloropropane		NA		NA		NA		NA		NA		NA		NA
cis-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA		NA
Dibromochloromethane		NA		NA		NA		NA		NA		NA		NA
1,1,2-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA		NA
trans-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA		NA
Bromoform		NA		NA		NA		NA		NA		NA		NA
4-Methyl-2-Pentanone		NA		NA		NA		NA		NA		NA		NA
2-Hexanone		NA		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA		NA
1,1,2,2-Tetrachloroethane		NA		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA		NA
Styrene		NA		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF004 (6")		BF005 (1')		BF005 (6")		BF006 (1')		BF006 (6")		BF007 (6")		BF007 (1.5')	
Sample Location	BF004		BF005		BF005		BF006		BF006		BF007		BF007	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Screening Analysis (UG/KG)														
Vinyl Chloride		NA		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA		NA

U - Not detected, UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF004 (6")		BF005 (1')		BF005 (6")		BF006 (1')		BF006 (6")		BF007 (6")		BF007 (1.5')	
Sample Location	BF004		BF005		BF005		BF006		BF006		BF007		BF007	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Semivolatile Organic Analysis (UG/KG)														
Phenol		NA		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethyl)ether		NA		NA		NA		NA		NA		NA		NA
2-Chlorophenol		NA		NA		NA		NA		NA		NA		NA
1,3-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
1,4-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
1,2-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
2-Methylphenol		NA		NA		NA		NA		NA		NA		NA
2,2'-oxybis(1-Chloropropane)		NA		NA		NA		NA		NA		NA		NA
4-Methylphenol		NA		NA		NA		NA		NA		NA		NA
N-Nitroso-di-n-propylamine		NA		NA		NA		NA		NA		NA		NA
Hexachloroethane		NA		NA		NA		NA		NA		NA		NA
Nitrobenzene		NA		NA		NA		NA		NA		NA		NA
Isophorone		NA		NA		NA		NA		NA		NA		NA
2-Nitrophenol		NA		NA		NA		NA		NA		NA		NA
2,4-Dimethylphenol		NA		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethoxy)methane		NA		NA		NA		NA		NA		NA		NA
2,4-Dichlorophenol		NA		NA		NA		NA		NA		NA		NA
1,2,4-Trichlorobenzene		NA		NA		NA		NA		NA		NA		NA
Naphthalene		NA		NA		NA		NA		NA		NA		NA
4-Chloroaniline		NA		NA		NA		NA		NA		NA		NA
Hexachlorobutadiene		NA		NA		NA		NA		NA		NA		NA
4-Chloro-3-methylphenol		NA		NA		NA		NA		NA		NA		NA
2-Methylnaphthalene		NA		NA		NA		NA		NA		NA		NA
Hexachlorocyclopentadiene		NA		NA		NA		NA		NA		NA		NA
2,4,6-Trichlorophenol		NA		NA		NA		NA		NA		NA		NA
2,4,5-Trichlorophenol		NA		NA		NA		NA		NA		NA		NA
2-Chloronaphthalene		NA		NA		NA		NA		NA		NA		NA
2-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
Dimethylphthalate		NA		NA		NA		NA		NA		NA		NA
Acenaphthylene		NA		NA		NA		NA		NA		NA		NA
2,6-Dinitrotoluene		NA		NA		NA		NA		NA		NA		NA
3-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
Acenaphthene		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF004 (6")		BF005 (1')		BF005 (6")		BF006 (1')		BF006 (6")		BF007 (6")		BF007 (1.5')	
Sample Location	BF004		BF005		BF005		BF006		BF006		BF007		BF007	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
2,4-Dinitrophenol		NA		NA		NA		NA		NA		NA		NA
4-Nitrophenol		NA		NA		NA		NA		NA		NA		NA
Dibenzofuran		NA		NA		NA		NA		NA		NA		NA
2,4-Dinitrotoluene		NA		NA		NA		NA		NA		NA		NA
Diethylphthalate		NA		NA		NA		NA		NA		NA		NA
4-Chlorophenyl-phenylether		NA		NA		NA		NA		NA		NA		NA
Fluorene		NA		NA		NA		NA		NA		NA		NA
4-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
4,6-Dinitro-2-methylphenol		NA		NA		NA		NA		NA		NA		NA
N-Nitroso-diphenylamine		NA		NA		NA		NA		NA		NA		NA
4-Bromophenyl-phenylether		NA		NA		NA		NA		NA		NA		NA
Hexachlorobenzene		NA		NA		NA		NA		NA		NA		NA
Pentachlorophenol		NA		NA		NA		NA		NA		NA		NA
Phenanthrene		NA		NA		NA		NA		NA		NA		NA
Anthracene		NA		NA		NA		NA		NA		NA		NA
Carbazole		NA		NA		NA		NA		NA		NA		NA
Di-n-Butylphthalate		NA		NA		NA		NA		NA		NA		NA
Fluoranthene		NA		NA		NA		NA		NA		NA		NA
Pyrene		NA		NA		NA		NA		NA		NA		NA
Butylbenzylphthalate		NA		NA		NA		NA		NA		NA		NA
3,3'-Dichlorobenzidine		NA		NA		NA		NA		NA		NA		NA
Benzo(a)anthracene		NA		NA		NA		NA		NA		NA		NA
Chrysene		NA		NA		NA		NA		NA		NA		NA
bis(2-Ethylhexyl)phthalate		NA		NA		NA		NA		NA		NA		NA
Di-n-octylphthalate		NA		NA		NA		NA		NA		NA		NA
Benzo(b)fluoranthene		NA		NA		NA		NA		NA		NA		NA
Benzo(k)fluoranthene		NA		NA		NA		NA		NA		NA		NA
Benzo(a)pyrene		NA		NA		NA		NA		NA		NA		NA
Indeno(1,2,3-cd)pyrene		NA		NA		NA		NA		NA		NA		NA
Dibenzo(a,h)anthracene		NA		NA		NA		NA		NA		NA		NA
Benzo(g,h,i)perylene		NA		NA		NA		NA		NA		NA		NA
Total PAH		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF004 (6")		BF005 (1')		BF005 (6")		BF006 (1')		BF006 (6")		BF007 (6")		BF007 (1.5')	
Sample Location	BF004		BF005		BF005		BF006		BF006		BF007		BF007	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)														
alpha-BHC		NA		NA		NA		NA		NA		NA		NA
beta-BHC		NA		NA		NA		NA		NA		NA		NA
delta-BHC		NA		NA		NA		NA		NA		NA		NA
gamma-BHC		NA		NA		NA		NA		NA		NA		NA
Heptachlor		NA		NA		NA		NA		NA		NA		NA
Aldrin		NA		NA		NA		NA		NA		NA		NA
Heptachlor Epoxide		NA		NA		NA		NA		NA		NA		NA
Endosulfan I		NA		NA		NA		NA		NA		NA		NA
Dieldrin		NA		NA		NA		NA		NA		NA		NA
4,4'-DDE		NA		NA		NA		NA		NA		NA		NA
Endrin		NA		NA		NA		NA		NA		NA		NA
Endosulfan II		NA		NA		NA		NA		NA		NA		NA
4,4'-DDD		NA		NA		NA		NA		NA		NA		NA
Endosulfan Sulfate		NA		NA		NA		NA		NA		NA		NA
4,4'-DDT		NA		NA		NA		NA		NA		NA		NA
Methoxychlor		NA		NA		NA		NA		NA		NA		NA
Endrin Ketone		NA		NA		NA		NA		NA		NA		NA
Endrin Aldehyde		NA		NA		NA		NA		NA		NA		NA
alpha-Chlordane		NA		NA		NA		NA		NA		NA		NA
gamma-Chlordane		NA		NA		NA		NA		NA		NA		NA
Toxaphene		NA		NA		NA		NA		NA		NA		NA
Aroclor-1016		NA		NA		NA		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA		NA		NA		NA
Aroclor-1242	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF
Aroclor-1248	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1254	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1260	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1262	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1268	2000	UF	16000	F	6000	F	2000	F	2000	UF	7000	F	2000	UF
Aroclor, Total	33	U	17066		7066		3066		33	U	8066		33	U

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF004 (6")		BF005 (1')		BF005 (6")		BF006 (1')		BF006 (6")		BF007 (6")		BF007 (1.5')	
Sample Location	BF004		BF005		BF005		BF006		BF006		BF007		BF007	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
TAL Metal Analysis (MG/KG)														
Aluminum		NA		NA		NA		NA		NA		NA		NA
Antimony		NA		NA		NA		NA		NA		NA		NA
Arsenic		NA		NA		NA		NA		NA		NA		NA
Barium		NA		NA		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA		NA		NA		NA
Calcium		NA		NA		NA		NA		NA		NA		NA
Chromium		NA		NA		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA		NA		NA		NA
Copper		NA		NA		NA		NA		NA		NA		NA
Iron		NA		NA		NA		NA		NA		NA		NA
Lead		NA		NA		NA		NA		NA		NA		NA
Magnesium		NA		NA		NA		NA		NA		NA		NA
Manganese		NA		NA		NA		NA		NA		NA		NA
Mercury		NA		NA		NA		NA		NA		NA		NA
Nickel		NA		NA		NA		NA		NA		NA		NA
Potassium		NA		NA		NA		NA		NA		NA		NA
Selenium		NA		NA		NA		NA		NA		NA		NA
Silver		NA		NA		NA		NA		NA		NA		NA
Sodium		NA		NA		NA		NA		NA		NA		NA
Thallium		NA		NA		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA		NA		NA		NA
Zinc		NA		NA		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)														
Lead	320		200		1410		5300		295		3360		1040	
Asbestos Analysis (%)														
Asbestos		NA		NA		NA		NA		NA		NA		NA
Total Organic Carbon Analysis (MG/KG)														
Total Organic Carbon		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF008 (6")		BF008 (1.5')		BF009 (1')		BF009 (6")		BF010 (1')		BF010 (6")		BF011 (6")	
Sample Location	BF008		BF008		BF009		BF009		BF010		BF010		BF011	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Analysis (UG/KG)														
Chloromethane		NA		NA		NA		NA		NA		NA		NA
Bromomethane		NA		NA		NA		NA		NA		NA		NA
Vinyl Chloride		NA		NA		NA		NA		NA		NA		NA
Chloroethane		NA		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA		NA
Acetone		NA		NA		NA		NA		NA		NA		NA
Carbon Disulfide		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA		NA
Chloroform		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
2-Butanone		NA		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Carbon Tetrachloride		NA		NA		NA		NA		NA		NA		NA
Bromodichloromethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloropropane		NA		NA		NA		NA		NA		NA		NA
cis-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA		NA
Dibromochloromethane		NA		NA		NA		NA		NA		NA		NA
1,1,2-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA		NA
trans-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA		NA
Bromoform		NA		NA		NA		NA		NA		NA		NA
4-Methyl-2-Pentanone		NA		NA		NA		NA		NA		NA		NA
2-Hexanone		NA		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA		NA
1,1,2,2-Tetrachloroethane		NA		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA		NA
Styrene		NA		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA		NA

U - Not detected, UJ - Detection limit approximate; J - Quantitation approximate;
* From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF008 (6")		BF008 (1.5')		BF009 (1')		BF009 (6")		BF010 (1')		BF010 (6")		BF011 (6")	
Sample Location	BF008		BF008		BF009		BF009		BF010		BF010		BF011	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Screening Analysis (UG/KG)														
Vinyl Chloride		NA		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF008 (6")		BF008 (1.5')		BF009 (1')		BF009 (6")		BF010 (1')		BF010 (6")		BF011 (6")	
Sample Location	BF008		BF008		BF009		BF009		BF010		BF010		BF011	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Semivolatile Organic Analysis (UG/KG)														
Phenol		NA		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethyl)ether		NA		NA		NA		NA		NA		NA		NA
2-Chlorophenol		NA		NA		NA		NA		NA		NA		NA
1,3-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
1,4-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
1,2-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
2-Methylphenol		NA		NA		NA		NA		NA		NA		NA
2,2'-oxybis(1-Chloropropane)		NA		NA		NA		NA		NA		NA		NA
4-Methylphenol		NA		NA		NA		NA		NA		NA		NA
N-Nitroso-di-n-propylamine		NA		NA		NA		NA		NA		NA		NA
Hexachloroethane		NA		NA		NA		NA		NA		NA		NA
Nitrobenzene		NA		NA		NA		NA		NA		NA		NA
Isophorone		NA		NA		NA		NA		NA		NA		NA
2-Nitrophenol		NA		NA		NA		NA		NA		NA		NA
2,4-Dimethylphenol		NA		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethoxy)methane		NA		NA		NA		NA		NA		NA		NA
2,4-Dichlorophenol		NA		NA		NA		NA		NA		NA		NA
1,2,4-Trichlorobenzene		NA		NA		NA		NA		NA		NA		NA
Naphthalene		NA		NA		NA		NA		NA		NA		NA
4-Chloroaniline		NA		NA		NA		NA		NA		NA		NA
Hexachlorobutadiene		NA		NA		NA		NA		NA		NA		NA
4-Chloro-3-methylphenol		NA		NA		NA		NA		NA		NA		NA
2-Methylnaphthalene		NA		NA		NA		NA		NA		NA		NA
Hexachlorocyclopentadiene		NA		NA		NA		NA		NA		NA		NA
2,4,6-Trichlorophenol		NA		NA		NA		NA		NA		NA		NA
2,4,5-Trichlorophenol		NA		NA		NA		NA		NA		NA		NA
2-Chloronaphthalene		NA		NA		NA		NA		NA		NA		NA
2-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
Dimethylphthalate		NA		NA		NA		NA		NA		NA		NA
Acenaphthylene		NA		NA		NA		NA		NA		NA		NA
2,6-Dinitrotoluene		NA		NA		NA		NA		NA		NA		NA
3-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
Acenaphthene		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF008 (6")		BF008 (1.5')		BF009 (1')		BF009 (6")		BF010 (1')		BF010 (6")		BF011 (6")	
Sample Location	BF008		BF008		BF009		BF009		BF010		BF010		BF011	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
2,4-Dinitrophenol		NA		NA		NA		NA		NA		NA		NA
4-Nitrophenol		NA		NA		NA		NA		NA		NA		NA
Dibenzofuran		NA		NA		NA		NA		NA		NA		NA
2,4-Dinitrotoluene		NA		NA		NA		NA		NA		NA		NA
Diethylphthalate		NA		NA		NA		NA		NA		NA		NA
4-Chlorophenyl-phenylether		NA		NA		NA		NA		NA		NA		NA
Fluorene		NA		NA		NA		NA		NA		NA		NA
4-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
4,6-Dinitro-2-methylphenol		NA		NA		NA		NA		NA		NA		NA
N-Nitroso-diphenylamine		NA		NA		NA		NA		NA		NA		NA
4-Bromophenyl-phenylether		NA		NA		NA		NA		NA		NA		NA
Hexachlorobenzene		NA		NA		NA		NA		NA		NA		NA
Pentachlorophenol		NA		NA		NA		NA		NA		NA		NA
Phenanthrene		NA		NA		NA		NA		NA		NA		NA
Anthracene		NA		NA		NA		NA		NA		NA		NA
Carbazole		NA		NA		NA		NA		NA		NA		NA
Di-n-Butylphthalate		NA		NA		NA		NA		NA		NA		NA
Fluoranthene		NA		NA		NA		NA		NA		NA		NA
Pyrene		NA		NA		NA		NA		NA		NA		NA
Butylbenzylphthalate		NA		NA		NA		NA		NA		NA		NA
3,3'-Dichlorobenzidine		NA		NA		NA		NA		NA		NA		NA
Benzo(a)anthracene		NA		NA		NA		NA		NA		NA		NA
Chrysene		NA		NA		NA		NA		NA		NA		NA
bis(2-Ethylhexyl)phthalate		NA		NA		NA		NA		NA		NA		NA
Di-n-octylphthalate		NA		NA		NA		NA		NA		NA		NA
Benzo(b)fluoranthene		NA		NA		NA		NA		NA		NA		NA
Benzo(k)fluoranthene		NA		NA		NA		NA		NA		NA		NA
Benzo(a)pyrene		NA		NA		NA		NA		NA		NA		NA
Indeno(1,2,3-cd)pyrene		NA		NA		NA		NA		NA		NA		NA
Dibenzo(a,h)anthracene		NA		NA		NA		NA		NA		NA		NA
Benzo(g,h,i)perylene		NA		NA		NA		NA		NA		NA		NA
Total PAH		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF008 (6")		BF008 (1.5')		BF009 (1')		BF009 (6")		BF010 (1')		BF010 (6")		BF011 (6")	
Sample Location	BF008		BF008		BF009		BF009		BF010		BF010		BF011	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)														
alpha-BHC		NA		NA		NA		NA		NA		NA		NA
beta-BHC		NA		NA		NA		NA		NA		NA		NA
delta-BHC		NA		NA		NA		NA		NA		NA		NA
gamma-BHC		NA		NA		NA		NA		NA		NA		NA
Heptachlor		NA		NA		NA		NA		NA		NA		NA
Aldrin		NA		NA		NA		NA		NA		NA		NA
Heptachlor Epoxide		NA		NA		NA		NA		NA		NA		NA
Endosulfan I		NA		NA		NA		NA		NA		NA		NA
Dieldrin		NA		NA		NA		NA		NA		NA		NA
4,4'-DDE		NA		NA		NA		NA		NA		NA		NA
Endrin		NA		NA		NA		NA		NA		NA		NA
Endosulfan II		NA		NA		NA		NA		NA		NA		NA
4,4'-DDD		NA		NA		NA		NA		NA		NA		NA
Endosulfan Sulfate		NA		NA		NA		NA		NA		NA		NA
4,4'-DDT		NA		NA		NA		NA		NA		NA		NA
Methoxychlor		NA		NA		NA		NA		NA		NA		NA
Endrin Ketone		NA		NA		NA		NA		NA		NA		NA
Endrin Aldehyde		NA		NA		NA		NA		NA		NA		NA
alpha-Chlordane		NA		NA		NA		NA		NA		NA		NA
gamma-Chlordane		NA		NA		NA		NA		NA		NA		NA
Toxaphene		NA		NA		NA		NA		NA		NA		NA
Aroclor-1016		NA		NA		NA		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA		NA		NA		NA
Aroclor-1242	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF
Aroclor-1248	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1254	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1260	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1262	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1268	4000	F	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF
Aroclor, Total	5066		33	U	33	U	33	U	33	U	33	U	33	U

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF008 (6")		BF008 (1.5')		BF009 (1')		BF009 (6")		BF010 (1')		BF010 (6")		BF011 (6")	
Sample Location	BF008		BF008		BF009		BF009		BF010		BF010		BF011	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
TAL Metal Analysis (MG/KG)														
Aluminum		NA		NA		NA		NA		NA		NA		NA
Antimony		NA		NA		NA		NA		NA		NA		NA
Arsenic		NA		NA		NA		NA		NA		NA		NA
Barium		NA		NA		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA		NA		NA		NA
Calcium		NA		NA		NA		NA		NA		NA		NA
Chromium		NA		NA		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA		NA		NA		NA
Copper		NA		NA		NA		NA		NA		NA		NA
Iron		NA		NA		NA		NA		NA		NA		NA
Lead		NA		NA		NA		NA		NA		NA		NA
Magnesium		NA		NA		NA		NA		NA		NA		NA
Manganese		NA		NA		NA		NA		NA		NA		NA
Mercury		NA		NA		NA		NA		NA		NA		NA
Nickel		NA		NA		NA		NA		NA		NA		NA
Potassium		NA		NA		NA		NA		NA		NA		NA
Selenium		NA		NA		NA		NA		NA		NA		NA
Silver		NA		NA		NA		NA		NA		NA		NA
Sodium		NA		NA		NA		NA		NA		NA		NA
Thallium		NA		NA		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA		NA		NA		NA
Zinc		NA		NA		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)														
Lead	935		200		200		200		200		200		250	
Asbestos Analysis (%)														
Asbestos		NA		NA		NA		NA		NA		NA		NA
Total Organic Carbon Analysis (MG/KG)														
Total Organic Carbon		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF012 (6")		BF013 (6")		BF014 (6")		BF015 (6")		BF016 (6")		BF017 (6")		BF018 (6")	
Sample Location	BF012		BF013		BF014		BF015		BF016		BF017		BF018	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Analysis (UG/KG)														
Chloromethane		NA		NA		NA		NA		NA		NA		NA
Bromomethane		NA		NA		NA		NA		NA		NA		NA
Vinyl Chloride		NA		NA		NA		NA		NA		NA		NA
Chloroethane		NA		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA		NA
Acetone		NA		NA		NA		NA		NA		NA		NA
Carbon Disulfide		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA		NA
Chloroform		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
2-Butanone		NA		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Carbon Tetrachloride		NA		NA		NA		NA		NA		NA		NA
Bromodichloromethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloropropane		NA		NA		NA		NA		NA		NA		NA
cis-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA		NA
Dibromochloromethane		NA		NA		NA		NA		NA		NA		NA
1,1,2-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA		NA
trans-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA		NA
Bromoform		NA		NA		NA		NA		NA		NA		NA
4-Methyl-2-Pentanone		NA		NA		NA		NA		NA		NA		NA
2-Hexanone		NA		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA		NA
1,1,2,2-Tetrachloroethane		NA		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA		NA
Styrene		NA		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF012 (6")		BF013 (6")		BF014 (6")		BF015 (6")		BF016 (6")		BF017 (6")		BF018 (6")	
Sample Location	BF012		BF013		BF014		BF015		BF016		BF017		BF018	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Screening Analysis (UG/KG)														
Vinyl Chloride		NA		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF012 (6")		BF013 (6")		BF014 (6")		BF015 (6")		BF016 (6")		BF017 (6")		BF018 (6")	
Sample Location	BF012		BF013		BF014		BF015		BF016		BF017		BF018	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Semivolatile Organic Analysis (UG/KG)														
Phenol		NA		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethyl)ether		NA		NA		NA		NA		NA		NA		NA
2-Chlorophenol		NA		NA		NA		NA		NA		NA		NA
1,3-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
1,4-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
1,2-Dichlorobenzene		NA		NA		NA		NA		NA		NA		NA
2-Methylphenol		NA		NA		NA		NA		NA		NA		NA
2,2'-oxybis(1-Chloropropane)		NA		NA		NA		NA		NA		NA		NA
4-Methylphenol		NA		NA		NA		NA		NA		NA		NA
N-Nitroso-di-n-propylamine		NA		NA		NA		NA		NA		NA		NA
Hexachloroethane		NA		NA		NA		NA		NA		NA		NA
Nitrobenzene		NA		NA		NA		NA		NA		NA		NA
Isophorone		NA		NA		NA		NA		NA		NA		NA
2-Nitrophenol		NA		NA		NA		NA		NA		NA		NA
2,4-Dimethylphenol		NA		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethoxy)methane		NA		NA		NA		NA		NA		NA		NA
2,4-Dichlorophenol		NA		NA		NA		NA		NA		NA		NA
1,2,4-Trichlorobenzene		NA		NA		NA		NA		NA		NA		NA
Naphthalene		NA		NA		NA		NA		NA		NA		NA
4-Chloroaniline		NA		NA		NA		NA		NA		NA		NA
Hexachlorobutadiene		NA		NA		NA		NA		NA		NA		NA
4-Chloro-3-methylphenol		NA		NA		NA		NA		NA		NA		NA
2-Methylnaphthalene		NA		NA		NA		NA		NA		NA		NA
Hexachlorocyclopentadiene		NA		NA		NA		NA		NA		NA		NA
2,4,6-Trichlorophenol		NA		NA		NA		NA		NA		NA		NA
2,4,5-Trichlorophenol		NA		NA		NA		NA		NA		NA		NA
2-Chloronaphthalene		NA		NA		NA		NA		NA		NA		NA
2-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
Dimethylphthalate		NA		NA		NA		NA		NA		NA		NA
Acenaphthylene		NA		NA		NA		NA		NA		NA		NA
2,6-Dinitrotoluene		NA		NA		NA		NA		NA		NA		NA
3-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
Acenaphthene		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF012 (6")		BF013 (6")		BF014 (6")		BF015 (6")		BF016 (6")		BF017 (6")		BF018 (6")	
Sample Location	BF012		BF013		BF014		BF015		BF016		BF017		BF018	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
2,4-Dinitrophenol		NA		NA		NA		NA		NA		NA		NA
4-Nitrophenol		NA		NA		NA		NA		NA		NA		NA
Dibenzofuran		NA		NA		NA		NA		NA		NA		NA
2,4-Dinitrotoluene		NA		NA		NA		NA		NA		NA		NA
Diethylphthalate		NA		NA		NA		NA		NA		NA		NA
4-Chlorophenyl-phenylether		NA		NA		NA		NA		NA		NA		NA
Fluorene		NA		NA		NA		NA		NA		NA		NA
4-Nitroaniline		NA		NA		NA		NA		NA		NA		NA
4,6-Dinitro-2-methylphenol		NA		NA		NA		NA		NA		NA		NA
N-Nitroso-diphenylamine		NA		NA		NA		NA		NA		NA		NA
4-Bromophenyl-phenylether		NA		NA		NA		NA		NA		NA		NA
Hexachlorobenzene		NA		NA		NA		NA		NA		NA		NA
Pentachlorophenol		NA		NA		NA		NA		NA		NA		NA
Phenanthrene		NA		NA		NA		NA		NA		NA		NA
Anthracene		NA		NA		NA		NA		NA		NA		NA
Carbazole		NA		NA		NA		NA		NA		NA		NA
Di-n-Butylphthalate		NA		NA		NA		NA		NA		NA		NA
Fluoranthene		NA		NA		NA		NA		NA		NA		NA
Pyrene		NA		NA		NA		NA		NA		NA		NA
Butylbenzylphthalate		NA		NA		NA		NA		NA		NA		NA
3,3'-Dichlorobenzidine		NA		NA		NA		NA		NA		NA		NA
Benzo(a)anthracene		NA		NA		NA		NA		NA		NA		NA
Chrysene		NA		NA		NA		NA		NA		NA		NA
bis(2-Ethylhexyl)phthalate		NA		NA		NA		NA		NA		NA		NA
Di-n-octylphthalate		NA		NA		NA		NA		NA		NA		NA
Benzo(b)fluoranthene		NA		NA		NA		NA		NA		NA		NA
Benzo(k)fluoranthene		NA		NA		NA		NA		NA		NA		NA
Benzo(a)pyrene		NA		NA		NA		NA		NA		NA		NA
Indeno(1,2,3-cd)pyrene		NA		NA		NA		NA		NA		NA		NA
Dibenzo(a,h)anthracene		NA		NA		NA		NA		NA		NA		NA
Benzo(g,h,i)perylene		NA		NA		NA		NA		NA		NA		NA
Total PAH		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF012 (6")		BF013 (6")		BF014 (6")		BF015 (6")		BF016 (6")		BF017 (6")		BF018 (6")	
Sample Location	BF012		BF013		BF014		BF015		BF016		BF017		BF018	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
Pesticide/PCB Analysis (UG/KG)														
alpha-BHC		NA		NA		NA		NA		NA		NA		NA
beta-BHC		NA		NA		NA		NA		NA		NA		NA
delta-BHC		NA		NA		NA		NA		NA		NA		NA
gamma-BHC		NA		NA		NA		NA		NA		NA		NA
Heptachlor		NA		NA		NA		NA		NA		NA		NA
Aldrin		NA		NA		NA		NA		NA		NA		NA
Heptachlor Epoxide		NA		NA		NA		NA		NA		NA		NA
Endosulfan I		NA		NA		NA		NA		NA		NA		NA
Dieldrin		NA		NA		NA		NA		NA		NA		NA
4,4'-DDE		NA		NA		NA		NA		NA		NA		NA
Endrin		NA		NA		NA		NA		NA		NA		NA
Endosulfan II		NA		NA		NA		NA		NA		NA		NA
4,4'-DDD		NA		NA		NA		NA		NA		NA		NA
Endosulfan Sulfate		NA		NA		NA		NA		NA		NA		NA
4,4'-DDT		NA		NA		NA		NA		NA		NA		NA
Methoxychlor		NA		NA		NA		NA		NA		NA		NA
Endrin Ketone		NA		NA		NA		NA		NA		NA		NA
Endrin Aldehyde		NA		NA		NA		NA		NA		NA		NA
alpha-Chlordane		NA		NA		NA		NA		NA		NA		NA
gamma-Chlordane		NA		NA		NA		NA		NA		NA		NA
Toxaphene		NA		NA		NA		NA		NA		NA		NA
Aroclor-1016		NA		NA		NA		NA		NA		NA		NA
Aroclor-1221		NA		NA		NA		NA		NA		NA		NA
Aroclor-1232		NA		NA		NA		NA		NA		NA		NA
Aroclor-1242	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF
Aroclor-1248	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1254	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1260	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1262	33	U	33	U	33	U	33	U	33	U	33	U	33	U
Aroclor-1268	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF	2000	UF
Aroclor, Total	33	U	33	U	33	U	33	U	33	U	33	U	33	U

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF012 (6")		BF013 (6")		BF014 (6")		BF015 (6")		BF016 (6")		BF017 (6")		BF018 (6")	
Sample Location	BF012		BF013		BF014		BF015		BF016		BF017		BF018	
Date Sampled														
QC Identifier	None		None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil		Soil	
TAL Metal Analysis (MG/KG)														
Aluminum		NA		NA		NA		NA		NA		NA		NA
Antimony		NA		NA		NA		NA		NA		NA		NA
Arsenic		NA		NA		NA		NA		NA		NA		NA
Barium		NA		NA		NA		NA		NA		NA		NA
Beryllium		NA		NA		NA		NA		NA		NA		NA
Cadmium		NA		NA		NA		NA		NA		NA		NA
Calcium		NA		NA		NA		NA		NA		NA		NA
Chromium		NA		NA		NA		NA		NA		NA		NA
Cobalt		NA		NA		NA		NA		NA		NA		NA
Copper		NA		NA		NA		NA		NA		NA		NA
Iron		NA		NA		NA		NA		NA		NA		NA
Lead		NA		NA		NA		NA		NA		NA		NA
Magnesium		NA		NA		NA		NA		NA		NA		NA
Manganese		NA		NA		NA		NA		NA		NA		NA
Mercury		NA		NA		NA		NA		NA		NA		NA
Nickel		NA		NA		NA		NA		NA		NA		NA
Potassium		NA		NA		NA		NA		NA		NA		NA
Selenium		NA		NA		NA		NA		NA		NA		NA
Silver		NA		NA		NA		NA		NA		NA		NA
Sodium		NA		NA		NA		NA		NA		NA		NA
Thallium		NA		NA		NA		NA		NA		NA		NA
Vanadium		NA		NA		NA		NA		NA		NA		NA
Zinc		NA		NA		NA		NA		NA		NA		NA
Metal Screening by XRF Analysis (MG/KG)														
Lead	200		200		200		250		200		200		320	
Asbestos Analysis (%)														
Asbestos		NA		NA		NA		NA		NA		NA		NA
Total Organic Carbon Analysis (MG/KG)														
Total Organic Carbon		NA		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF019 (6")		BF020 (6")		BF021 (1')		BF021 (6")		BF022 (6")		OU2-SB-216-0305	
Sample Location	BF019		BF020		BF021		BF021		BF022		SB-216	
Date Sampled											9/23/97	
QC Identifier	None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Analysis (UG/KG)												
Chloromethane		NA		NA		NA		NA		NA		NA
Bromomethane		NA		NA		NA		NA		NA		NA
Vinyl Chloride		NA		NA		NA		NA		NA		NA
Chloroethane		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA
Acetone		NA		NA		NA		NA		NA		NA
Carbon Disulfide		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA
Chloroform		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA
2-Butanone		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA
Carbon Tetrachloride		NA		NA		NA		NA		NA		NA
Bromodichloromethane		NA		NA		NA		NA		NA		NA
1,2-Dichloropropane		NA		NA		NA		NA		NA		NA
cis-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA
Dibromochloromethane		NA		NA		NA		NA		NA		NA
1,1,2-Trichloroethane		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA
trans-1,3-Dichloropropene		NA		NA		NA		NA		NA		NA
Bromoform		NA		NA		NA		NA		NA		NA
4-Methyl-2-Pentanone		NA		NA		NA		NA		NA		NA
2-Hexanone		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA
1,1,2,2-Tetrachloroethane		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA
Styrene		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF019 (6")		BF020 (6")		BF021 (1')		BF021 (6")		BF022 (6")		OU2-SB-216-0305	
Sample Location	BF019		BF020		BF021		BF021		BF022		SB-216	
Date Sampled											9/23/97	
QC Identifier	None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil	
Volatile Organic Screening Analysis (UG/KG)												
Vinyl Chloride		NA		NA		NA		NA		NA		NA
Methylene Chloride		NA		NA		NA		NA		NA		NA
1,1-Dichloroethene		NA		NA		NA		NA		NA		NA
1,1-Dichloroethane		NA		NA		NA		NA		NA		NA
1,2-Dichloroethene (total)		NA		NA		NA		NA		NA		NA
1,2-Dichloroethane		NA		NA		NA		NA		NA		NA
1,1,1-Trichloroethane		NA		NA		NA		NA		NA		NA
Trichloroethene		NA		NA		NA		NA		NA		NA
Benzene		NA		NA		NA		NA		NA		NA
Tetrachloroethene		NA		NA		NA		NA		NA		NA
Toluene		NA		NA		NA		NA		NA		NA
Chlorobenzene		NA		NA		NA		NA		NA		NA
Ethylbenzene		NA		NA		NA		NA		NA		NA
Total Xylenes		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF019 (6")		BF020 (6")		BF021 (1')		BF021 (6")		BF022 (6")		OU2-SB-216-0305	
Sample Location	BF019		BF020		BF021		BF021		BF022		SB-216	
Date Sampled											9/23/97	
QC Identifier	None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil	
Semivolatile Organic Analysis (UG/KG)												
Phenol		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethyl)ether		NA		NA		NA		NA		NA		NA
2-Chlorophenol		NA		NA		NA		NA		NA		NA
1,3-Dichlorobenzene		NA		NA		NA		NA		NA		NA
1,4-Dichlorobenzene		NA		NA		NA		NA		NA		NA
1,2-Dichlorobenzene		NA		NA		NA		NA		NA		NA
2-Methylphenol		NA		NA		NA		NA		NA		NA
2,2'-oxybis(1-Chloropropane)		NA		NA		NA		NA		NA		NA
4-Methylphenol		NA		NA		NA		NA		NA		NA
N-Nitroso-di-n-propylamine		NA		NA		NA		NA		NA		NA
Hexachloroethane		NA		NA		NA		NA		NA		NA
Nitrobenzene		NA		NA		NA		NA		NA		NA
Isophorone		NA		NA		NA		NA		NA		NA
2-Nitrophenol		NA		NA		NA		NA		NA		NA
2,4-Dimethylphenol		NA		NA		NA		NA		NA		NA
Bis(2-Chloroethoxy)methane		NA		NA		NA		NA		NA		NA
2,4-Dichlorophenol		NA		NA		NA		NA		NA		NA
1,2,4-Trichlorobenzene		NA		NA		NA		NA		NA		NA
Naphthalene		NA		NA		NA		NA		NA		NA
4-Chloroaniline		NA		NA		NA		NA		NA		NA
Hexachlorobutadiene		NA		NA		NA		NA		NA		NA
4-Chloro-3-methylphenol		NA		NA		NA		NA		NA		NA
2-Methylnaphthalene		NA		NA		NA		NA		NA		NA
Hexachlorocyclopentadiene		NA		NA		NA		NA		NA		NA
2,4,6-Trichlorophenol		NA		NA		NA		NA		NA		NA
2,4,5-Trichlorophenol		NA		NA		NA		NA		NA		NA
2-Chloronaphthalene		NA		NA		NA		NA		NA		NA
2-Nitroaniline		NA		NA		NA		NA		NA		NA
Dimethylphthalate		NA		NA		NA		NA		NA		NA
Acenaphthylene		NA		NA		NA		NA		NA		NA
2,6-Dinitrotoluene		NA		NA		NA		NA		NA		NA
3-Nitroaniline		NA		NA		NA		NA		NA		NA
Acenaphthene		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Analytical Results - Soil
Remedial Investigation Report
Raymark OU4 - Ballfield Site
Stratford, Connecticut

Sample Number	BF019 (6")		BF020 (6")		BF021 (1')		BF021 (6")		BF022 (6")		OU2-SB-216-0305	
Sample Location	BF019		BF020		BF021		BF021		BF022		SB-216	
Date Sampled											9/23/97	
QC Identifier	None		None		None		None		None		None	
Matrix	Soil		Soil		Soil		Soil		Soil		Soil	
2,4-Dinitrophenol		NA		NA		NA		NA		NA		NA
4-Nitrophenol		NA		NA		NA		NA		NA		NA
Dibenzofuran		NA		NA		NA		NA		NA		NA
2,4-Dinitrotoluene		NA		NA		NA		NA		NA		NA
Diethylphthalate		NA		NA		NA		NA		NA		NA
4-Chlorophenyl-phenylether		NA		NA		NA		NA		NA		NA
Fluorene		NA		NA		NA		NA		NA		NA
4-Nitroaniline		NA		NA		NA		NA		NA		NA
4,6-Dinitro-2-methylphenol		NA		NA		NA		NA		NA		NA
N-Nitroso-diphenylamine		NA		NA		NA		NA		NA		NA
4-Bromophenyl-phenylether		NA		NA		NA		NA		NA		NA
Hexachlorobenzene		NA		NA		NA		NA		NA		NA
Pentachlorophenol		NA		NA		NA		NA		NA		NA
Phenanthrene		NA		NA		NA		NA		NA		NA
Anthracene		NA		NA		NA		NA		NA		NA
Carbazole		NA		NA		NA		NA		NA		NA
Di-n-Butylphthalate		NA		NA		NA		NA		NA		NA
Fluoranthene		NA		NA		NA		NA		NA		NA
Pyrene		NA		NA		NA		NA		NA		NA
Butylbenzylphthalate		NA		NA		NA		NA		NA		NA
3,3'-Dichlorobenzidine		NA		NA		NA		NA		NA		NA
Benzo(a)anthracene		NA		NA		NA		NA		NA		NA
Chrysene		NA		NA		NA		NA		NA		NA
bis(2-Ethylhexyl)phthalate		NA		NA		NA		NA		NA		NA
Di-n-octylphthalate		NA		NA		NA		NA		NA		NA
Benzo(b)fluoranthene		NA		NA		NA		NA		NA		NA
Benzo(k)fluoranthene		NA		NA		NA		NA		NA		NA
Benzo(a)pyrene		NA		NA		NA		NA		NA		NA
Indeno(1,2,3-cd)pyrene		NA		NA		NA		NA		NA		NA
Dibenzo(a,h)anthracene		NA		NA		NA		NA		NA		NA
Benzo(g,h,i)perylene		NA		NA		NA		NA		NA		NA
Total PAH		NA		NA		NA		NA		NA		NA

U - Not detected; UJ - Detection limit approximate; J - Quantitation approximate;
* - From dilution analysis; R - Rejected; NA - Not Analyzed

Appendix C Analytical Results
(pages 35-74)
is available
in a separate file (size: 4.1 MB)

Click here to view.

Appendix C Analytical Results
(pages 75-119)
is available
in a separate file (size: 4.8 MB)

Click here to view.

Appendix C Analytical Results
(pages 120-164)
is available
in a separate file (size: 4.8 MB)

Click here to view.

Appendix C Analytical Results
(pages 165-208)
is available
in a separate file (size: 4.7 MB)

Click here to view.

Appendix C Analytical Results
(pages 209-256)
is available
in a separate file (size: 5.0 MB)

Click here to view.