


NEXT STEPS/TIMELINE FIVE POINTS PCE PLUME



Note: This type of site has been addressed by this process before. There is a similar site called the “Bountiful Woods Cross 5th South PCE Plume” Site. The remedial specialists have had experience with similar geology and issues that occur at this site.