

**Documentation of Environmental Indicator Determination
in accordance with EPA Interim Final Guidance 2/5/99**

**RCRA Corrective Action
Environmental Indicator (EI) RCRIS code (CA750)**

Migration of Contaminated Groundwater Under Control

Facility Name: Safety-Kleen
Facility Address: Springfield, MO
Facility EPA ID #: MOD 000 669 069

1. Has **all** available relevant/significant information on known and reasonably suspected releases to the groundwater media, subject to RCRA Corrective Action (e.g., from Solid Waste Management Units (SWMU), Regulated Units (RU), and Areas of Concern (AOC)), been **considered** in this EI determination?

 X If yes - check here and continue with #2 below.

 If no - re-evaluate existing data, or

If data are not available, skip to #8 and enter "IN" (more information needed) status code.

BACKGROUND

Definition of Environmental Indicators (for RCRA Corrective Action)

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EIs developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Migration of Contaminated Groundwater Under Control" EI

A positive "Migration of Contaminated Groundwater Under Control" EI determination ("YE" status code) indicates that the migration of "contaminated" groundwater has stabilized, and that monitoring will be conducted to confirm that contaminated groundwater remains within the original "area of contaminated groundwater" (for all groundwater "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action

program the EIs are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA). The "Migration of Contaminated Groundwater Under Control" EI pertains ONLY to the physical migration (i.e., further spread) of contaminated groundwater and contaminants within groundwater (e.g., non-aqueous phase liquids or NAPLs). Achieving this EI does not substitute for achieving other stabilization or final remedy requirements and expectations associated with sources of contamination and the need to restore, wherever practicable, contaminated groundwater to be suitable for its designated current and future uses.

Duration / Applicability of EI Determinations

EI Determination status codes should remain in RCRIS national database ONLY as long as they remain true (i.e., RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

2. Is **groundwater** known or reasonably suspected to be "**contaminated**"¹ above appropriately protective "levels" (i.e., applicable promulgated standards, as well as other appropriate standards, guidelines, guidance, or criteria) from releases subject to RCRA Corrective Action, anywhere at, or from, the facility?

If yes - continue after identifying key contaminants, citing appropriate "levels," and referencing supporting documentation.

If no - skip to #8 and enter "YE" status code, after citing appropriate "levels," and referencing supporting documentation to demonstrate that groundwater is not "contaminated."

If unknown - skip to #8 and enter "IN" status code.

Rationale and Reference(s): Dissolved-phase VOCs (cis 1,2 DCE, chlorobenzene and vinyl chloride) in groundwater have been detected on-site slightly above applicable Drinking Water MCLs and Missouri Water Quality Standards of 0.07 mg/l, 0.1 mg/l, and 0.002 mg/l, respectively (Attached is a summary of groundwater sample analytical results from 11/1994 to 11/1998).

Footnotes:

¹"Contamination" and "contaminated" describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriate "levels" (appropriate for the protection of the groundwater resource and its beneficial uses).

3. Has the **migration** of contaminated groundwater **stabilized** (such that contaminated groundwater is expected to remain within "existing area of contaminated groundwater"² as defined by the monitoring locations designated at the time of this determination)?

 X If yes - continue, after presenting or referencing the physical evidence (e.g., groundwater sampling/measurement/migration barrier data) and rationale why contaminated groundwater is expected to remain within the (horizontal or vertical) dimensions of the "existing area of groundwater contamination"²).

 If no (contaminated groundwater is observed or expected to migrate beyond the designated locations defining the "existing area of groundwater contamination"²) - skip to #8 and enter "NO" status code, after providing an explanation.

 If unknown - skip to #8 and enter "IN" status code.

Rationale and Reference(s): The extent of groundwater contamination has been completely defined through semi-annual groundwater sampling and analysis of total VOCs since 1994. VOCs have only been detected on-site in a shallow saturated zone, and the concentrations trend of VOCs has declined as a result of S-K's operation of groundwater extraction system from 1995 to 1998. VOCs have not been detected at the on-site perimeter wells and are not likely to migrate off-site based on S-K's past extraction of the mass load of VOCs, contaminant source removal and low aquifer transmissivity and storage coefficients. The groundwater plume has stabilized on-site and total VOCs concentration trends in groundwater have decreased considerably since monitoring was first initiated at the site in 1994 (see attached summary of groundwater sample analytical results from 11/1994 to 11/1998, and isoconcentration map for total VOCs). Detailed information concerning the nature and extent of groundwater contamination may be found in the approved Revised Interim Corrective Measure Report Addendum, dated November 20, 1997, in the MDNR Hazardous Waste Program's TSD files and EPA Region VII files.

² "existing area of contaminated groundwater" is an area (with horizontal and vertical dimensions) that has been verifiably demonstrated to contain all relevant groundwater contamination for this determination, and is defined by designated (monitoring) locations proximate to the outer perimeter of "contamination" that can and will be sampled/tested in the future to physically verify that all "contaminated" groundwater remains within this area, and that the further migration of "contaminated" groundwater is not occurring. Reasonable allowances in the proximity of the monitoring locations are permissible to incorporate formal remedy

decisions (i.e., including public participation) allowing a limited area for natural attenuation.

4. Does "contaminated" groundwater **discharge** into **surface water** bodies?

_____ If yes - continue after identifying potentially affected surface water bodies.

 X If no - skip to #7 (and enter a "YE" status code in #8, if #7 = yes) after providing an explanation and/or referencing documentation supporting that groundwater "contamination" does not enter surface water bodies.

_____ If unknown - skip to #8 and enter "IN" status code.

Rationale and Reference(s): Contaminated groundwater is detected only on-site at relatively low concentrations slightly above groundwater protection standards and is unlikely to migrate off-site. No surface water bodies or groundwater discharges have been identified on-/near-site during investigation of past releases. No VOC contamination has been detected in the perimeter wells including downgradient wells MW-2 and MW-8, and is not likely to migrate off-site.

5. Is the **discharge** of "contaminated" groundwater into surface water likely to be "**insignificant**" (i.e., the maximum concentration³ of each contaminant discharging into surface water is less than 10 times the appropriate groundwater "level," and there are no other conditions (e.g., the nature or number of discharging contaminants, or environmental setting), which significantly increase the potential for unacceptable impacts to surface water, sediments or eco-systems at these concentrations)?

_____ If yes - skip to #7 (and enter "YE" status code in #8 if #7 = yes), after documenting: 1) the maximum known or reasonably suspected concentration³ of key contaminants discharged above their groundwater "level," the value of the appropriate "level(s)," and if there is evidence that the concentrations are increasing; and 2) provide a statement of professional judgement/explanation (or reference documentation) supporting that the discharge of groundwater contaminants into the surface water is not anticipated to have unacceptable impacts to the receiving surface water, sediments or eco-system.

_____ if no - (the discharge of "contaminated" groundwater into surface water is potentially significant) - continue after documenting: 1) the maximum known or reasonably suspected concentration³ of each contaminant discharged above its groundwater "level," the value of the appropriate "level(s)," and if there is evidence that the concentrations are increasing;

and 2) for any contaminants discharging into surface water in concentrations³ greater than 100 times the appropriate groundwater "levels," the estimated total amount (mass in kg/yr) of each of these contaminants that are being discharged (loaded) into the surface water body (at the time of the determination), and identify if there is evidence that the amount of discharging contaminants is increasing.

_____ If unknown - enter "IN" status code in #8.

Rationale and Reference(s): _____

³ As measured in groundwater prior to entry to the groundwater-surface water/sediment interaction (e.g., hyporheic) zone.

6. Can the **discharge** of "contaminated" groundwater into surface water be shown to be "**currently acceptable**" (i.e., not cause impacts to surface water, sediments or eco-systems that should not be allowed to continue until a final remedy decision can be made and implemented⁴)?

_____ If yes - continue after either: 1) identifying the Final Remedy decision incorporating these conditions, or other site-specific criteria (developed for the protection of the site's surface water, sediments, and eco-systems), and referencing supporting documentation demonstrating that these criteria are not exceeded by the discharging groundwater; OR 2) providing or referencing an interim-assessment,⁵ appropriate to the potential for impact, that shows the discharge of groundwater contaminants into the surface water is (in the opinion of a trained specialist(s), including ecologist) adequately protective of receiving surface water, sediments, and eco-systems, until such time when a full assessment and final remedy decision can be made. Factors which should be considered in the interim-assessment (where appropriate to help identify the impact associated with discharging groundwater) include: surface water body size, flow, use/classification/habitats and contaminant loading limits, other sources of surface water/sediment contamination, surface water and sediment sample results and comparisons to available and appropriate surface water and sediment "levels," as well as any other factors, such as effects on ecological receptors (e.g., via bio-assays/benthic surveys or site-specific ecological Risk Assessments), that the overseeing regulatory agency would deem appropriate for making the EI determination.

_____ If no - (the discharge of "contaminated" groundwater cannot be shown to

be "**currently acceptable**") - skip to #8 and enter "NO" status code, after documenting the currently unacceptable impacts to the surface water body, sediments and/or eco-systems.

_____ If unknown - skip to 8 and enter "IN" status code.

Rationale and Reference(s) _____

⁴ Note, because areas of inflowing groundwater can be critical habitats (e.g., nurseries or thermal refugia) for many species, appropriate specialist (e.g., ecologist) should be included in management decisions that could eliminate these areas by significantly altering or reversing groundwater flow pathways near surface water bodies.

⁵ The understanding of the impacts of contaminated groundwater discharges into surface water bodies is a rapidly developing field and reviewers are encouraged to look to the latest guidance for the appropriate methods and scale of demonstration to be reasonably certain that discharges are not causing currently unacceptable impacts to the surface waters, sediments or eco-systems.

7. Will groundwater **monitoring** / measurement data (and surface water/sediment/ecological data, as necessary) be collected in the future to verify that contaminated groundwater has remained within the horizontal (or vertical, as necessary) dimensions of the "existing area of contaminated groundwater?"

 X If yes - continue after providing or citing documentation for planned activities or future sampling/measurement events. Specifically identify the well/measurement locations which will be tested in the future to verify the expectation (identified in #3) that groundwater contamination will not be migrating horizontally (or vertically, as necessary) beyond the "existing area of groundwater contamination."

_____ If no - enter "NO" status code in #8.

_____ If unknown - enter "IN" status code in #8.

Rationale and Reference(s): Based on relatively low groundwater contaminant concentrations, and lack of surface water bodies on-/near-site and lack of private potable drinking water wells with a ½ mile radius of the site, S-K proposed monitored natural attenuation with contingent retention of groundwater extraction system as final remedy. The groundwater monitoring program consists of semi-annual analysis of groundwater samples from six wells (MW-4, MW-5, MW-6, MW-7, RW-1 and RW-2) for VOCs and natural attenuation parameters to support evaluation of the effectiveness

of natural attenuation in addressing groundwater contamination and meeting applicable groundwater protection standards (Drinking Water MCLs and Missouri Water Quality Standards) while ensuring that no contaminants are migrating off-site. Groundwater monitoring is scheduled to continue on an annual basis for a period of three consecutive years after groundwater contaminants have met the protection standards. S-K's proposed final remedy is presented in the Corrective Measure Work Plan/Report dated July 6, 1999, in the MDNR Hazardous Waste Program's TSD files and EPA's Region VII files. Final approval of the CMS Work Plan/Report and preparation of a Statement of Basis for the proposed final remedy is pending.

- 8. Check the appropriate RCRIS status codes for the Migration of Contaminated Groundwater Under Control EI (event code CA750), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (attach appropriate supporting documentation as well as a map of the facility).

X YE - Yes, "Migration of Contaminated Groundwater Under Control" has been verified. Based on a review of the information contained in this EI determination, it has been determined that the "Migration of Contaminated Groundwater" is "Under Control" at the Safety-Kleen facility, EPA ID # MOD 000 669 069 , located at Springfield, MO . Specifically, this determination indicates that the migration of "contaminated" groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the "existing area of contaminated groundwater." This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

NO - Unacceptable migration of contaminated groundwater is observed or expected.

IN - More information is needed to make a determination.

Completed by: (Signature) Fuad Marmash Date 9/30/1999
(Print) Fuad Marmash
(Title) Environmental Engineer

Supervisor: (Signature) Richard A. Nussbaum Date 9/30/99
(Print) Richard A. Nussbaum, P.E., R.G.
(Title) Chief, Corrective Action Unit
(EPA Region or State) State - MO Dept. of Natural Resources -
 Hazardous Waste Program

Locations where References may be found:

The MDNR Hazardous Waste Program's TSD files and EPA's Region VII files.

Facility: Safety-Kleen, Springfield, MO
CA750
Page 8 of 8

Contact telephone and e-mail numbers

(Name) Fuad Marmash
(Phone #) (573) 751-0944
(E-mail) nrmarf@mail.dnr.state.mo.us

ref: **ca750epa.doc**