DOCUMENTATION OF ENVIRONMENTAL INDICATOR DETERMINATION RCRA Corrective Action Environmental Indicator (EI) RCRIS code (CA725) Current Human Exposures Under Control

Facility Name: Brightsmith Coil Coaters (Formerly MSC Engineered Materials and Solution Group)Facility Address: 120 Enterprise Ave., Morrisville, PA 19067Facility EPA ID #: PAD073739005

1. Has **all** available relevant/significant information on known and reasonably suspected releases to soil, groundwater, surface water/sediments, and air, subject to RCRA Corrective Action (e.g., from Solid Waste Management Units (SWMU), Regulated Units (RU), and Areas of Concern (AOC)), been **considered** in this EI determination?

\boxtimes	If yes - check here and continue with #2 below.
	If no - re-evaluate existing data, or
	if data are not available, skip to #8 and enter "IN" (more information needed) status code.

<u>BACKGROUND</u> <u>Definition of Environmental Indicators (for the RCRA Corrective Action)</u>

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EI developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Current Human Exposures Under Control" EI

A positive "Current Human Exposures Under Control" EI determination ("YE" status code) indicates that there are no "unacceptable" human exposures to "contamination" (i.e., contaminants in concentrations in excess of appropriate risk-based levels) that can be reasonably expected under current land- and groundwater-use conditions (for all "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action program the EI are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA). The "Current Human Exposures Under Control" EI are for reasonably expected human exposures under current land- and groundwater-use conditions ONLY, and do not consider potential future land- or groundwater-use conditions or ecological receptors. The RCRA Corrective Action program's overall mission to protect human health and the environment requires that Final remedies address these issues (i.e., potential future human exposure scenarios, future land and groundwater uses, and ecological receptors).

Duration / Applicability of EI Determinations

EI Determinations status codes should remain in RCRIS national database ONLY as long as they remain true (i.e., RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

2. Are groundwater, soil, surface water, sediments, or air **media** known or reasonably suspected to be **"contaminated"**¹ above appropriately protective risk-based "levels" (applicable promulgated standards, as well as other appropriate standards, guidelines, guidance, or criteria) from releases subject to RCRA Corrective Action (from SWMUs, RUs or AOCs)?

	Yes	No	?	Rationale / Key Contaminants
	100	1.0	<u> </u>	
Groundwater	Х			Toluene, Arsenic
Air (indoors) ²		Х		
Surface Soil (e.g., <2 ft)	Х			Hexavalent chromium, heavy metals
Surface Water		Х		
Sediment	Х			Cyanide, PCBs, heavy metals
Subsurf. Soil (e.g., >2 ft)	Х			Hexavalent chromium, heavy metals
Air (outdoors)		Х		

- If no (for all media) skip to #6, and enter "YE," status code after providing or citing appropriate "levels," and referencing sufficient supporting documentation demonstrating that these "levels" are not exceeded.
- If yes (for any media) continue after identifying key contaminants in each "contaminated" medium, citing appropriate "levels" (or provide an explanation for the determination that the medium could pose an unacceptable risk), and referencing supporting documentation.
- If unknown (for any media) skip to #6 and enter "IN" status code.

Rationale and Reference(s):

A sampling investigation was done between 12/2021 and 01/2022; groundwater, sediment, and soil samples were collected from previously identified Solid Waste Management Units (SWMU). Groundwater exceeded EPA National Primary Drinking Water Maximum Contaminant Levels (MCLs) for Toluene and Arsenic. Both surface and subsurface soil borings exceeded EPA Industrial Regional Screening Levels (RSL) for Hexavalent Chromium and Arsenic. Sediment samples were taken adjacent to the facilities outfall in an unnamed tributary to Biles Creek; an upstream sediment sample was also taken to provide background reference concentrations. Sediment at the outfall exceeded EPA Region III Freshwater Sediment Screening Benchmarks for Cyanide, Total Chromium, Total Copper, and Total Lead. Sediment from both samples were found to contain low concentrations of Total PCBs. There is not a known PCB source at the Facility; there is a pad-mounted transformer located on the property, however this has previously been investigated and dielectric fluid from the transformer tested and was found to be non-PCB containing.

Environmental Indicator Investigation Report. INTEX Environmental Group, Inc. March 02, 2022. *Environmental Indicator Inspection Report*. URS. January 2007. Footnotes:

¹ "Contamination" and "contaminated" describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriately protective risk-based "levels" (for the media, that identify risks within the acceptable risk range).

² Recent evidence (from the Colorado Dept. of Public Health and Environment, and others) suggest that unacceptable indoor air concentrations are more common in structures above groundwater with volatile contaminants than previously believed. This is a rapidly developing field and reviewers are encouraged to look to the latest guidance for the appropriate methods and scale of demonstration necessary to be reasonably certain that indoor air (in structures located above (and adjacent to) groundwater with volatile contaminants) does not present unacceptable risks.

3. Are there **complete pathways** between "contamination" and human receptors such that exposures can be reasonably expected under the current (land- and groundwater-use) conditions?

Summary Exposure Pathway Evaluation Table

Potential Human Receptors (Under Current Conditions)

"Contaminated" Media	Residents	Workers	Day-Care	Construction	Trespassers	Recreation	Food ³
Groundwater	No	No	No	Yes	No	No	No
Air (indoors)	-	-	-	-	-	-	-
Soil (surface, e.g., <2 ft)	No	Yes	No	Yes	Yes	No	No
Surface Water	-	-	-	-	-	-	-
Sediment	No	No	No	Yes	Yes	No	No
Soil (subsurface e.g., >2 ft)	No	No	No	Yes	No	No	No
Air (outdoors)	-	-	-	-	-	-	-

Instructions for **Summary Exposure Pathway Evaluation Table**:

1. Strike-out specific Media including Human Receptors' spaces for Media which are not "contaminated" as identified in #2 above.

2. enter "yes" or "no" for potential "completeness" under each "Contaminated" Media -- Human Receptor combination (Pathway).

Note: In order to focus the evaluation to the most probable combinations some potential "Contaminated" Media - Human Receptor combinations (Pathways) do not have check spaces ("____"). While these combinations may not be probable in most situations, they may be possible in some settings and should be added as necessary.

- If no (pathways are not complete for any contaminated media-receptor combination) skip to #6, and enter "YE" status code, after explaining and/or referencing condition(s) in-place, whether natural or manmade, preventing a complete exposure pathway from each contaminated medium (e.g., use optional Pathway Evaluation Work Sheet to analyze major pathways).
- If yes (pathways are complete for any "Contaminated" Media Human Receptor combination) continue after providing supporting explanation.
- If unknown (for any "Contaminated" Media Human Receptor combination) skip to #6 and enter "IN" status code.

Rationale and Reference(s):

Workers, construction workers, and trespassers may be exposed to surface soil contamination via direct contact or inhalation of dust particles. Construction workers may be exposed to surface soil, subsurface soil, sediment, or groundwater contamination via direct contact or inhalation of dust particles during excavation activities. Trespassers may also be exposed to sediment contamination via direct contact or incidental ingestion. There is not a daycare located in the vicinity of the facility. The facility is located within an industrial park, so there is no recreational activity on the property. There are a few residences that rely on private wells for potable water however they are located approximately 1.7 miles West from the facility on the opposite side of Van Sciver Lake, and groundwater flow on the property is in the S-SW direction, thus groundwater exposure to residents is unlikely

Environmental Indicator Inspection Report. URS. January 2007.

³ Indirect Pathway/Receptor (e.g., vegetables, fruits, crops, meat and dairy products, fish, shellfish, etc.)

- 4. Can the **exposures** from any of the complete pathways identified in #3 be reasonably expected to be "**significant**"⁴ (i.e., potentially "unacceptable" because exposures can be reasonably expected to be: 1) greater in magnitude (intensity, frequency and/or duration) than assumed in the derivation of the acceptable "levels" (used to identify the "contamination"); or 2) the combination of exposure magnitude (perhaps even though low) and contaminant concentrations (which may be substantially above the acceptable "levels") could result in greater than acceptable risks)?
 - If no (exposures can not be reasonably expected to be significant (i.e., potentially "unacceptable") for any complete exposure pathway) skip to #6 and enter "YE" status code after explaining and/or referencing documentation justifying why the exposures (from each of the complete pathways) to "contamination" (identified in #3) are not expected to be "significant."
 - If yes (exposures could be reasonably expected to be "significant" (i.e., potentially "unacceptable") for any complete exposure pathway) - continue after providing a description (of each potentially "unacceptable" exposure pathway) and explaining and/or referencing documentation justifying why the exposures (from each of the remaining complete pathways) to "contamination" (identified in #3) are not expected to be "significant."
 - If unknown (for any complete pathway) skip to #6 and enter "IN" status code

Rationale and Reference(s):

 \square

Exposure to human receptors is not reasonably expected to be greater in magnitude than assumed in the derivation of the acceptable levels based on the activity of this facility and the surrounding industrial area. The contaminant concentrations in soil and groundwater fall within EPA's acceptable risk range of 10^{-6} to 10^{-4} and therefore are not anticipated to pose greater than acceptable risk to human health based upon results of the most recent sampling data.

⁴ If there is any question on whether the identified exposures are "significant" (i.e., potentially "unacceptable") consult a human health Risk Assessment specialist with appropriate education, training and experience.

5.	Can the	e "significant" exposures (identified in #4) be shown to be within acceptable limits?					
		If yes (all "significant" exposures have been shown to be within acceptable limits) - continue and enter "YE" after summarizing <u>and</u> referencing documentation justifying why all "significant" exposures to "contamination" are within acceptable limits (e.g., a site-specific Human Health Risk Assessment).					
		If no - (there are current exposures that can be reasonably expected to be "unacceptable")- continue and enter "NO" status code after providing a description of each potentially "unacceptable" exposure.					
		If unknown (for any potentially "unacceptable" exposure) - continue and enter "IN" status code.					
Rational	e and Re	ference(s):					

6. Check the appropriate RCRIS status codes for the Current Human Exposures Under Control EI (event code CA725), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (attach appropriate supporting documentation as well as a map of the facility).

\boxtimes	YE - Yes, "Current Human Exposures Under Control" has been verified. Based on a review of
	the information contained in this EI Determination, "Current Human Exposures" are expected to
	be "Under Control" at the Brightsmith Coil Coaters facility, EPA ID # PAD073739005, located
	at 120 Enterprise Ave., Morrisville, PA 19067 under current and reasonably expected conditions.
	This determination will be re-evaluated when the Agency/State becomes aware of significant
	changes at the facility.

NO - "Current Human Exposures" are NOT "Under Control."

IN - More information is needed to make a determination.

Completed by

Date 06/01/2022

Date

Kristin Koroncai Remedial Project Manager

Supervisor

Alizabeth Olhasso Chief, RCRA Corrective Action Branch 2 EPA Region 3

Locations where References may be found:

US EPA Region III Land, Chemicals, and Redevelopment Division 4 Penn Center 1600 JFK Boulevard Philadelphia, PA 19103

Contact telephone and e-mail numbers

Kristin Koroncai 215-814-2711 Koroncai.kristin@epa.gov