
TABLE OF CONTENTS

Section	Page
EXECUTIVE SUMMARY	ES-1
1. INTRODUCTION.....	1-1
1.1 PURPOSE	1-1
1.1.1 Basis for EE/CA	1-2
1.1.2 EE/CA Approach.....	1-2
1.1.3 Comparison of EE/CA and RI/FS Processes.....	1-4
1.2 EPA SUMMARY OF AGREEMENT	1-4
1.3 REPORT ORGANIZATION	1-8
2. SITE CHARACTERIZATION.....	2-1
2.1 SITE DESCRIPTION AND BACKGROUND	2-1
2.1.1 Site Location and Description of Subreaches.....	2-3
2.1.2 Watershed Characteristics	2-4
2.1.2.1 Population	2-5
2.1.2.2 Land Use.....	2-5
2.1.2.3 Climate	2-5
2.1.2.4 Regional Geologic Setting.....	2-6
2.1.2.5 Hydrology.....	2-8
2.1.2.6 Historic Morphology	2-12
2.1.3 Subreach Characteristics	2-14
2.1.3.1 Morphology	2-14
2.1.3.2 Streambed Composition	2-15
2.1.3.3 Geologic Setting	2-17
2.1.3.4 Land Use/Access	2-19
2.1.3.5 Habitat Assessment	2-21
2.2 PREVIOUS REMOVAL ACTIONS	2-25
2.2.1 Building 68 Area	2-25
2.2.2 Other Removal Actions	2-26
2.2.3 1999 Removal Action.....	2-28
2.3 SOURCE, NATURE, AND EXTENT OF CONTAMINATION	2-30
2.3.1 Historic GE Operations/Status of Source Reach.....	2-31
2.3.1.1 GE Plant Site	2-32
2.3.1.2 Interior Landfill	2-33
2.3.1.3 Former Waste Stabilization Basin.....	2-33
2.3.1.4 Hill 78 Landfill	2-34
2.3.1.5 Underground Storage Tanks.....	2-34
2.3.1.6 Housatonic River.....	2-35
2.3.1.7 Silver Lake	2-36

TABLE OF CONTENTS (Continued)

Section	Page
2.3.1.8 Former Oxbows.....	2-37
2.3.2 PCB Sources Within the EE/CA Reach	2-38
2.3.3 River Sediment.....	2-38
2.3.4 Riverbank Soils	2-39
2.3.5 Summary of PCB Distribution	2-41
2.3.6 Specialty Samples.....	2-42
2.3.7 Appendix IX Data	2-46
2.3.7.1 Sediment Samples	2-46
2.3.7.2 Riverbank Samples.....	2-48
2.3.8 Oil Sample.....	2-49
2.4 STREAMLINED RISK ASSESSMENT	2-50
2.4.1 Human Health Risk Assessment	2-51
2.4.2 Ecological Risk Assessment.....	2-53
3. IDENTIFICATION OF REMOVAL ACTION SCOPE, GOALS, AND OBJECTIVES	3-1
3.1 STATUTORY LIMITS ON REMOVAL ACTIONS	3-1
3.2 APPLICABLE OR RELEVANT AND APPROPRIATE REQUIREMENTS	3-1
3.3 REMOVAL ACTION OBJECTIVES.....	3-2
3.4 DETERMINATION OF REMOVAL ACTION SCOPE.....	3-4
3.4.1 Determination of Excavation Volumes	3-6
3.4.1.1 Sediment.....	3-6
3.4.1.2 Riverbank Soils	3-7
3.5 DETERMINATION OF REMOVAL ACTION SCHEDULE	3-9
4. IDENTIFICATION AND SCREENING OF TECHNOLOGIES.....	4-1
4.1 SCREENING CRITERIA	4-1
4.2 RIVER DIVERSION AND SEDIMENT AND RIVERBANK SOIL REMOVAL TECHNOLOGIES	4-3
4.2.1 River Diversion	4-4
4.2.1.1 Open Channel Diversion (Intrusive—Sheetpiling)	4-4
4.2.1.2 Open Channel Diversion (Nonintrusive).....	4-4
4.2.1.3 Gravity Feed Bypass Pipe.....	4-5
4.2.1.4 Bypass Pump and Piping.....	4-6
4.2.1.5 Alternate River Channel.....	4-6
4.2.2 Sediment and Riverbank Soil Removal Technologies	4-7
4.2.2.1 Wet Excavation	4-7
4.2.2.2 Dredging from a Barge	4-7
4.2.2.3 Dry Excavation.....	4-8

TABLE OF CONTENTS

(Continued)

Section	Page
4.2.3 River Diversion and Sediment/Soil Removal Screening	4-8
4.2.4 Conclusions	4-9
4.2.4.1 River Diversion Technologies.....	4-9
4.2.4.2 Sediment Removal Technologies.....	4-10
4.3 IN SITU TREATMENT/CONTAINMENT TECHNOLOGIES FOR SOILS AND SEDIMENTS.....	4-11
4.3.1 In Situ Containment	4-11
4.3.1.1 In Situ Containment of Bank Soil	4-12
4.3.1.2 In Situ Containment of River Sediment	4-12
4.3.2 Chemical Immobilization.....	4-14
4.3.3 Biological Treatment.....	4-14
4.3.4 In Situ Technologies—Summary of Detailed Screening Results.....	4-15
4.4 EX SITU TREATMENT TECHNOLOGIES FOR SOILS AND SEDIMENTS.....	4-16
4.4.1 Physical/Chemical Treatment.....	4-16
4.4.1.1 Soil Washing	4-17
4.4.1.2 Solvent Extraction.....	4-18
4.4.1.3 Stabilization/Solidification.....	4-18
4.4.1.4 Chemical Dechlorination.....	4-19
4.4.2 Thermal Treatment.....	4-19
4.4.2.1 Incineration.....	4-19
4.4.2.2 Thermal Desorption.....	4-20
4.4.3 Biological Treatment.....	4-21
4.4.4 Ex Situ Treatment Technologies – Summary of Detailed Screening Results .	4-21
4.5 EX SITU CONSOLIDATION/DISPOSAL	4-22
4.5.1 Off-Site Disposal.....	4-22
4.5.1.1 Reuse of Material as Landfill Cover	4-22
4.5.1.2 Disposal at a RCRA Subtitle D Landfill	4-23
4.5.1.3 Disposal at a RCRA Subtitle C Landfill	4-24
4.5.1.4 Disposal at a TSCA-Approved Landfill.....	4-25
4.5.1.5 Off-Site Treatment and Disposal.....	4-25
4.5.1.6 Disposal of Debris.....	4-26
4.5.2 On-Site Consolidation at GE Facility, Pittsfield	4-26
4.5.3 Ex Situ Consolidation/Disposal Technologies – Summary of Detailed Screening Results	4-27
4.6 RESTORATION	4-27
4.6.1 Riverbank Restoration Technologies	4-29
4.6.1.1 Revegetation.....	4-30
4.6.1.2 Bioengineered Structures	4-32
4.6.1.3 Hard Structures.....	4-34

TABLE OF CONTENTS (Continued)

Section	Page
4.6.2 Riverbed Restoration Technologies	4-35
4.6.2.1 Pool/Riffle Construction	4-35
4.6.2.2 Aquatic Cover	4-37
4.6.2.3 Erosion Protection	4-38
4.6.2.4 Improving Substrate Conditions.....	4-38
4.7 SUMMARY OF RETAINED TECHNOLOGIES	4-39
4.7.1 River Diversion	4-39
4.7.2 Sediment Removal	4-40
4.7.3 Treatment and Consolidation/Disposal Technologies.....	4-40
4.7.4 Restoration	4-41
5. IDENTIFICATION AND ANALYSIS OF REMOVAL ALTERNATIVES FOR THE EE/CA REACH.....	5-1
5.1 ALTERNATIVES EVALUATION CRITERIA.....	5-3
5.1.1 Effectiveness	5-4
5.1.2 Implementability	5-4
5.1.3 Cost	5-5
5.2 BASE ALTERNATIVE 1—WET EXCAVATION TO MEET CLEANUP CRITERIA.....	5-5
5.2.1 Base Alternative 1 Description.....	5-6
5.2.1.1 Mobilization, Site Preparation, and River Access.....	5-6
5.2.1.2 Excavation.....	5-8
5.2.1.3 Confirmation Sampling	5-11
5.2.1.4 Handling, Transportation, and Stockpile Management.....	5-12
5.2.1.5 Dewatering of Excavated Materials	5-13
5.2.1.6 Restoration of Riverbed	5-14
5.2.1.7 Restoration of Riverbanks.....	5-17
5.2.1.8 Sampling of Stockpiles.....	5-20
5.2.1.9 Consolidation, Disposal, and Treatment Options.....	5-20
5.2.2 Alternative 1 Evaluations	5-30
5.2.2.1 Base Alternative 1 Effectiveness.....	5-30
5.2.2.2 Effectiveness of Options A, B, C, and D.....	5-31
5.2.2.3 Base Alternative 1 Implementability.....	5-35
5.2.2.4 Implementability of Options A, B, C, and D.....	5-36
5.2.2.5 Cost of Alternatives 1A, 1B, 1C, and 1D	5-40
5.3 BASE ALTERNATIVE 2—DRY EXCAVATION TO MEET CLEANUP CRITERIA/ DIVERSION BY SHEETPILING AND PUMPING BYPASS.....	5-40
5.3.1 Base Alternative 2 Description.....	5-41
5.3.1.1 Mobilization, Site Preparation, and River Access.....	5-41
5.3.1.2 Installation of Sheetpiling	5-42

TABLE OF CONTENTS (Continued)

Section	Page
5.3.1.3 Installation of Pumping Bypass.....	5-45
5.3.1.4 Dewatering of Riverbed	5-46
5.3.1.5 Dry Excavation of Sediments and Soils	5-47
5.3.1.6 Confirmation Sampling	5-48
5.3.1.7 Handling, Transportation, and Stockpile Management.....	5-48
5.3.1.8 Dewatering of Excavated Materials	5-48
5.3.1.9 Restoration of Riverbed	5-48
5.3.1.10 Restoration of Riverbanks.....	5-48
5.3.1.11 Sampling of Stockpiles.....	5-48
5.3.1.12 Consolidation, Disposal, and Treatment Options.....	5-48
5.3.2 Alternative 2 Evaluations	5-49
5.3.2.1 Base Alternative 2 Effectiveness.....	5-49
5.3.2.2 Effectiveness of Options A, B, C, and D.....	5-51
5.3.2.3 Base Alternative 2 Implementability.....	5-51
5.3.2.4 Implementability of Options A, B, C, and D.....	5-52
5.3.2.5 Cost of Alternatives 2A, 2B, 2C, and 2D.....	5-52
5.4 BASE ALTERNATIVE 3—DRY EXCAVATION TO MEET CLEANUP CRITERIA/ DIVERSION BY PUMPING BYPASS.....	5-53
5.4.1 Base Alternative 3 Description.....	5-53
5.4.1.1 Mobilization, Site Preparation, and River Access.....	5-53
5.4.1.2 Pumping Bypass Along Entire EE/CA Reach.....	5-54
5.4.1.3 Dewatering of Riverbed	5-54
5.4.1.4 Dry Excavation of Sediments and Soils	5-54
5.4.1.5 Confirmation Sampling	5-54
5.4.1.6 Handling, Transportation, and Stockpile Management.....	5-54
5.4.1.7 Dewatering of Excavated Materials	5-54
5.4.1.8 Restoration of Riverbed	5-54
5.4.1.9 Restoration of Riverbanks.....	5-55
5.4.1.10 Sampling of Stockpiles.....	5-55
5.4.1.11 Consolidation, Disposal, and Treatment Options.....	5-55
5.4.2 Alternative 3 Evaluations	5-56
5.4.2.1 Base Alternative 3 Effectiveness.....	5-56
5.4.2.2 Effectiveness of Options A, B, C, and D.....	5-57
5.4.2.3 Base Alternative 3 Implementability.....	5-57
5.4.2.4 Implementability of Options A, B, C, and D.....	5-58
5.4.2.5 Cost of Alternatives 3A, 3B, 3C, and 3D	5-58
5.5 COMPARISON OF ALTERNATIVES	5-59
5.5.1 Effectiveness	5-60
5.5.1.1 Protection of Human Health and the Environment	5-60
5.5.1.2 Compliance with ARARs.....	5-61

TABLE OF CONTENTS (Continued)

Section	Page
5.5.1.3 Long-Term Effectiveness and Permanence.....	5-62
5.5.1.4 Reduction of Toxicity, Mobility, or Volume Through Treatment	5-63
5.5.1.5 Short-Term Effectiveness.....	5-63
5.5.2 IMPLEMENTABILITY	5-65
5.5.2.1 Technical Feasibility	5-66
5.5.2.2 Availability of Services and Materials	5-68
5.5.2.3 Administrative Feasibility	5-68
5.5.3 Cost	5-69
6. RECOMMENDED REMOVAL ACTION ALTERNATIVE.....	6-1
7. TABLES	7-1
8. FIGURES	8-1
9. REFERENCES.....	9-1

LIST OF APPENDICES

APPENDIX A—COMBINED ACTION AND EE/CA APPROVAL MEMORANDUM

APPENDIX B—EE/CA COST ESTIMATES

APPENDIX C—ARARs TABLES

APPENDIX D—HISTORIC SITE INFORMATION

APPENDIX E—GRAIN SIZE ANALYSIS DATA

APPENDIX F—BORING LOGS AND GEOTECHNICAL DATA

APPENDIX G—SEDIMENT DATA

APPENDIX H—RIVERBANK SOIL DATA

APPENDIX I—SPECIALTY SAMPLE ANALYTICAL DATA

APPENDIX J—APPENDIX IX ANALYTICAL DATA-RIVERBANK SOIL AND SEDIMENT

APPENDIX K—HOUSATONIC RIVER AND RIPARIAN COMMUNITY CHARACTERIZATION: LYMAN STREET TO THE CONFLUENCE

APPENDIX L—RESTORATION DESIGN SCENARIOS

APPENDIX M—CAP DESIGN AND CONSTRUCTION EVALUATION

APPENDIX N—BANK STABILITY EVALUATION

APPENDIX O—ESTIMATE OF EXCAVATION AND BACKFILL

APPENDIX P—RESTORATION MONITORING PLAN OUTLINE

APPENDIX Q—MISCELLANEOUS INFORMATION

LIST OF TABLES

Title

- Table 1.1-1 Comparison of EE/CA to RI/FS
- Table 2.1-1 Summary of Physical Characteristics
- Table 2.1-2 Summary of Grain Size Distribution Results
- Table 2.1-3 Summary of Cobble Sampling Results
- Table 2.3-1 Summary of Average PCB Concentrations
- Table 2.3-2 Summary of 95% UCL PCB Concentrations
- Table 2.3-3 Summary of PCB Mass Distribution
- Table 2.3-4 Summary of DRET and Pore Water Results
- Table 2.3-5 Summary of PCB Fractionation Data
- Table 2.3-6 Summary of Appendix IX Results for Sediment
- Table 2.3-7 Appendix IX Riverbank Soil Comparison to Standards
- Table 2.3-8 Summary of Appendix IX Riverbank Soil Samples that Exceed Standards
- Table 3.4-1 Summary of Excavation Depths and Sediment and Riverbank Soil Volumes To Be Removed
- Table 3.4-2 Summary of Excavation Areas and Depths
- Table 3.4-3 95% UCL PCB Concentrations for Sediments Remaining After Excavation to Cleanup Goals
- Table 3.4-4 Summary of Non-Subreach Area PCB Data
- Table 3.4-5 Evaluation of Areas with Exceedance Percentages < 25%
- Table 3.4-6 Summary of PCB Data for Riverbank Soils Remaining After Hotspot Removal
- Table 4.1-1 Screening of River Diversion Technologies
- Table 4.1-2 Screening of Sediment and Riverbank Soil Removal Technologies

LIST OF TABLES **(Continued)**

- Table 4.1-3a Screening of Treatment/In Situ Containment Technologies
- Table 4.1-3b Screening of Consolidation/Disposal Technologies
- Table 4.1-4 Potential Bank Restoration Technologies
- Table 4.1-5 Potential Riverbed Restoration Technologies
- Table 4.1-6 Summary of Retained Technologies Following Technology Screening
- Table 4.3-1 95% UCL PCB Concentration for Comparison of Capping Versus Excavation to Cleanup Goal
- Table 5.5-1 Summary of Detailed Comparison of Base Alternatives 1, 2, and 3
- Table 5.5-2 Summary of Detailed Comparison of Disposal Options A, B, C, and D
- Table 5.5-3 Detailed Cost Summary for Base Alternatives 1, 2, and 3
- Table 5.5-4 Detailed Cost Summary for Consolidation/Disposal/Treatment Options A, B, C, and D
- Table 5.5-5 Comparative Cost Summary for Alternatives Incorporating Disposal Options

LIST OF FIGURES

Title

- Figure 1.1-1 EE/CA Development Process
- Figure 2.1-1 Location Map
- Figure 2.1-2 Subreach Location Map
- Figure 2.1-3 Average Daily Discharge: 1936-1996, Housatonic River, Coltsville Station
- Figure 2.1-4 Annual Peak River Discharge: 1936-1996, Housatonic River, Coltsville Station
- Figure 2.1-5 Response to Precipitation, Housatonic River, Coltsville Station
- Figure 2.1-6 Site Plan with Topography and Conceptual Construction Layout
- Figure 2.1-7 Specialty Sample Locations
- Figure 2.1-8 Sediment Thickness
- Figure 2.1-9 Schematic Geological Cross Section of the EE/CA Reach
- Figure 2.3-1 Source Areas Within the EE/CA Reach
- Figure 2.3-2 Sediment PCB Data (Subreaches 3-8, 3-9, 3-10, 4-1, 4-2, 4-3, 4-4A, 4-4B, 4-5A, 4-5B, and 4-6)
- Figure 2.3-3 Bank PCB Data (Subreaches 3-8, 3-9, 3-10, 4-1, 4-2, 4-3, 4-4A, 4-4B, 4-5A, 4-5B, and 4-6)
- Figure 2.3-4 Sediment and Bank Appendix IX Location Map
- Figure 3.4-1 Extent of Sediment Removal for Cleanup
- Figure 3.4-2 Evaluation of Riverbank Soil Remediation Areas: Decision Matrix
- Figure 3.4-3 Extent of Riverbank Soil Removal for Cleanup
- Figure 4.2-1 Summary Chart of River Diversion and Sediment Removal Screening
- Figure 4.3-1 Evaluation of Sediment Remedial Alternatives, Capping Versus Excavation to Cleanup Goals
- Figure 4.6-1 Typical Slope Regrading

LIST OF FIGURES **(Continued)**

Figure 4.6-2 Wattling Details

Figure 4.6-3 Brush Layering Method

Figure 4.6-4 Brush Matting Details

Figure 4.6-5 Streambank Stabilization with Dormant Posts and Stakes

Figure 4.6-6 Gravel Riffle

Figure 4.6-7 Current Deflectors

Figure 4.6-8 Boulder Placement

Figure 5.2-1 River Excavation Conceptual Cross Section

Figure 5.2-2 Remedial Process Flow Sheet – Disposal Option C, Thermal Desorption

Figure 5.2-3 Remedial Process Flow Sheet – Disposal Option D, Solvent Extraction