



Photograph 1 – Placement of Bin Blocks Upstream of Lyman Street as Part of Remediation Cell No. 1A



Photograph 2 – Placement of Sheet Pile Driving Platform in River



Photograph 3 – Installation of Sheet Pile Wall Immediately Downstream of the Lyman Street Bridge



Photograph 4 – Excavation of Sediments at Cell 1A Beneath Lyman Street Bridge