Photograph 1 – Cell 11 Excavation Activities

Photograph 2 – Cell 11 Excavation Activities

Photograph 3 – Installation of Permanent Sheetpile Retaining Wall in Cell 11

Photograph 4 – Cell 11, Backfilling Riverbank with Common Fill Filter Grade

Photograph 5– Cell 11, Compacting Common Fill Filter Layer on the Riverbank

Photograph 6– Cell 11, Installation of the Geoweb

Photograph 7– Cell 11, Placement of Topsoil in the Geoweb

Photograph 8– Cell 11, Placement of Topsoil in the Geoweb

Photograph 9– Cell 11, Placement of Topsoil in the Geoweb

Photograph 10– Cell 11, Riprap Slope Covering Permanent Sheetpile Retaining Wall

Photograph 11– Cell 9, Restoration 100% Complete

Photograph 12– Overview of Complete Final Restoration (except for trees & shrubs)