


Figure 5.9.2-3

Kendall Station intake continuous temperatures compared with continuous temperatures measured near the Boston University Bridge. Temperatures taken once a day in the same location by the Massachusetts Water Resources Authority (MWRA) were also included (July - September, 1999).



Data Source: Mirant Kendall and MWRA Provisional Data

1999 Intake Temps    MWRA Data    MRI Continuous BU Bridge