

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Billerica, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
<i>MA82A-07_2008</i>	Concord River	Concord	5			3.9	10.4	Exotic species* Metals Nutrients Pathogens	
<i>MA82A-08_2008</i>	Concord River	Concord	5			2.9	5.1	Exotic species* Metals Nutrients	
<i>MA83-09_2008</i>	Content Brook	Shawsheen	2			1.4	2.4		
<i>MA83-14_2008</i>	Spring Brook	Shawsheen	4a			0.1	2.6		
<i>MA83-17_2008</i>	Shawsheen River	Shawsheen	5			3.0	5.7	Pathogens	CN122.0
<i>MA83-18_2008</i>	Shawsheen River	Shawsheen	5			1.9	10.1	Organic enrichment/Low DO Pathogens	CN122.0
								Metals Organic enrichment/Low DO	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Billerica, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
<i>MA92-05_2008</i>	Lubbers Brook	Ipswich	2			1.0	6.3	Pathogens	CN122.0
<i>MA82088_2008</i>	Nutting Lake	Concord	5	30.48	30.48			Exotic species* Mercury Pathogens	NEHgTMDL
<i>MA82123_2008</i>	Winning Pond	Concord	4c	22.22	22.22				
<i>MA82124_2008</i>	Nutting Lake	Concord	4a	51.41	51.41			Mercury	NEHgTMDL
<i>MA83020_2008</i>	Richardson Pond North	Shawsheen	3	3.51	45.78				
<i>MA83021_2008</i>	Pond Street Pond	Shawsheen	3	3.56	3.56				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries