

# Attachment 1

## Photo Documentation

Former Rockwell Corp. Site  
Allegan, Michigan



Remnants of clay sewer line near MH-11. 7/27/06



Remnants of clay sewer line near MH-11. 7/27/06



Remnants of clay sewer line near MH-11. 7/27/06



Remnants of clay sewer line near MH-11. 7/27/06



Remnants of clay sewer line near MH-11. 7/27/06



Remnants of clay sewer line near MH-11. 7/27/06



Remnants of clay sewer line near MH-11. 7/27/06



Remnants of clay sewer line near MH-11. 7/27/06



Sewer line excavation looking south. 7/27/06



Cementing remnants of clay sewer line near MH-11. 7/27/06



Cementing remnants of clay sewer line near MH-11. 7/27/06



Sewer line excavation looking south. 7/27/06



Sewer line excavation looking south. 7/27/06



Rockwell site looking northwest. 8/4/06



Trucks dumping backfill sand for grading and finishing purposes. 8/4/06



Rockwell site looking northeast. 8/4/06

