# Enclosure CLEAN AIR ACT MOBILE SOURCE EXPEDITED SETTLEMENT AGREEMENT

DOCKET NO. AED-17-8327 Respondent:

Boost Diesel Repair LLC 13901 Kershaw Street Houston, TX 77037

- 1. The parties enter into this Clean Air Act Mobile Source Expedited Settlement Agreement (Agreement) in order to settle the civil violations discovered as a result of the inspection specified in Table 1, attached, incorporated into this Agreement by reference. The civil violations that are the subject of this Agreement are described in Table 2, attached, incorporated into the Agreement by reference, regarding the vehicles/engines specified therein.
- 2. Respondent admits to being subject to the Clean Air Act (CAA) and its associated regulations, and that the United States Environmental Protection Agency (EPA) has jurisdiction over the Respondent and the Respondent's conduct described in Table 2. Respondent does not contest the findings detailed therein, and waives any objections Respondent may have to the EPA's jurisdiction.
- 3. Respondent consents to the payment of a penalty in the amount of \$100, further described in Table 3, attached, incorporated into this Agreement by reference. Respondent agrees to follow the instructions in "CAA Mobile Source Expedited Settlement Agreement Instructions," attached, incorporated into this Agreement by reference. Respondent certifies that the required remediation, detailed in Table 3, has been carried out.
- 4. By its first signature below, the EPA approves the findings resulting from the inspection and the alleged violations set forth in Tables 1 and 2. Upon signing and returning this Agreement to the EPA, Respondent consents to the terms of this Agreement without further notice. Respondent acknowledges this Agreement is binding on the parties signing below, and becomes effective on the date of the EPA Air Enforcement Division Director's ratifying signature.

APPROVED BY EPA:	Date: May 19, 2017	
Phillip A. Brooks, Director, Air Enforcement Division		
APPROVED BY RESPONDENT:		
Name (print):		
Title (print):A		
Signature:	Date: 4/1/17	
RATHELED BY EPA:	, ,	
KAMILETA.	Date: 8/22/17	
W Phillip A. Brooks, Director, Air Enforcement Division		

Table 1 - Inspection Information			
Entry/Inspection Date(s):	Docket Number:		
September 22, 2016	C A A - 1 7 - 8 3 2 7		
Inspection Location: Entry/Inspection Number(s)			
13901 Kershaw Street	2 0 1 6 - 0 9 - 2 2 - 1 0 0 0		
City:	Inspector(s) Name(s):		
Houston	Doreen Au		
Ficusion	Bill Squier		
State: Zip Code: EPA Approving Official:			
TX 77037	Phillip A. Brooks		
Respondent:	EPA Enforcement Contact(s):		
P	Caitlin Meisenbach, Attorney-Adviser, (202) 565-0062		
Boost Diesel Repair LLC	Tony Miller, Chemical Engineer, (303) 312-7161		

#### Table 2 - Description of Violations and Vehicles/Engines

On September 22, 2016, authorized inspectors obtained evidence that Boost Diesel Repair LLC (Boost) had sold and installed products which render inoperative emission control systems on EPA-certified motor vehicles and motor vehicle engines. It is a violation of Section 203(a)(3) of the CAA, 42 U.S.C. § 7522(a)(3) to sell and install a defeat device, and to tamper with a EPA-certified motor vehicle or motor vehicle engine. From August 3, 2014, until September 20, 2016, the EPA has determined that fifteen (15) vehicles were altered in violation of Title II of the Clean Air Act (CAA) by Boost. The EPA has determined Boost committed thirty (30) violations of CAA § 203(a)(3), 42 U.S.C. § 7522(a)(3). These violations include selling and installing defeat devices; rendering inoperative On-Board Diagnostics; and removing Exhaust Gas Recirculation systems. Diesel Oxidation Catalysts, Diesel Particulate Filters, and Selective Catalytic Reduction systems.

er fere in felle men in der der eine verwerbeit der geben der felle felle eine Erfelte verwerf felle felle fel	Table 2 (cont): Description of Invoices, Engines, and Violations				
Count	Invoice Date	Year, Make, Model	VIN	Violations of CAA § 203(a)(3)	
I	8/3/2014	2006 Ford F-350 Super Duty	1FDWF36PX6EC81519	icos, sudanti da ante esperare esta de destructura de como como como como como como como com	
2	10/21/2015	2008 Ford F250	1FTSW21R68EA14824	2	
3	1/16/2016	2008 Dodge 3500	3D7KS28A18G242370	2	
4	2/2/2016	2012 Dodge RAM 3500	3C63DRNL7CG178844	2	
5	2/2/2016	2010 Ford F250	IFTSW2BR1AEA83473	. 2	
6	2/11/2016	2008 Ford F350	1FTWW33R28ED14512	2	
7	5/20/2016	2014 Dodge 3500	3C63RRJL2EG193634	2	
8	5/26/2016	2012 Dodge RAM 3500	3C7WDSCLXCG160437	2	
9	6/3/2016	2012 Dodge 3500	3C63DPGL2CG212805	7	
10	6/22/2016	2011 Ford F-250	1FT7W2BT8BEA72893	2	
1 1	6/24/2016	2008 Ford F-250	1FTSW21R38EA35307	2	
12	7/3/2016	2011 Dodge 2500	3D7UT2CL9BG637886	2	
13	7/14/2016	2008 Ford F-350	1FTWW31R28EB55462	ż	
14	7/29/2016	2011 Dodge RAM 3500	3D73M4CL6BG636702	2	
15	9/20/2016	2012 Dodge RAM 3500	3C63DRGL3CG110179	2	

Table 3 - Penalty and Required Remediation				
Penalty	\$100, based on a demonstrated inability to pay, in reliance on information provided by Boost			
Required Remediation	In addition to paying the monetary penalty, Boost must cease and refrain from purchasing, selling, and installing, any device that defeats, bypasses, or otherwise renders inoperative an emission component of any engine regulated by the EPA. Also, Boost must cease and refrain from tampering with emission control systems on EPA-certified motor vehicles and motor vehicle engines.			



# Receipt

# Your payment is complete

Pay.gov Tracking ID: 262PQ2N6 Agency Tracking ID: 75256132378

Form Name: EPA Miscellaneous Payments - Cincinnati Finance Center

Application Name: EPA Miscellaneous Payments

### **Payment Information**

Payment Type: Debit or credit card

Payment Amount: \$100.00

Transaction Date: 06/01/2017 11:46:47 AM EDT

Payment Date: 06/01/2017

#### **Account Information**

Cardholder Name: Boost Diesel Repair

Card Type: Visa

Card Number: \*\*\*\*\*\*\*\*8487

## **Email Confirmation Receipt**

Confirmation Receipts have been emailed to: BOOSTDIESELREPAIR@GMAIL.COM

EPA Fine