




- LEGEND:**
- x-x-x- FENCE
 - ⊗ MONITORING WELL
 - ⊠ TEMPORARY WELL
 - SOIL BORING
 - ▲ SOIL SAMPLE LOCATIONS
 - (0.89) TOTAL PCBs (mg/kg)
 - (ND) PCBs NOT DETECTED



HISTORICAL SOIL INVESTIGATION
0-3' FEET (2008)
**FORMER MCCANDLESS
FUELS SITE**

2231 Delsea Drive
Franklinville, New Jersey

<p>10 LIPPINCOTT LA. MT. HOLLY, NJ 08060 Tel. (856) 273-1009 Fax. (856) 273-1012 1-866-Remedi-8</p>	DESIGNED: JMM
	DETAILED: SGH
	CHECKED: JMM
SOURCE: DELTA McCandless-1	DATE: 3/13/2017
FILE NAME: 18016_DeltaSoil	JOB NO.: 18016
FIGURE: 5A	




LEGEND:

- x-x-x-x- FENCE
- ⊗ MONITORING WELL
- ⊠ TEMPORARY WELL
- SOIL BORING
- ▲ SOIL SAMPLE LOCATIONS
- (0.23) TOTAL PCBs (mg/kg)
- (ND) PCBs NOT DETECTED

PCB LEVELS:


- 100-1,000 mg/kg
- 10-100 mg/kg
- 1-10 mg/kg



HISTORICAL SOIL INVESTIGATION
3'-5' FEET (2008)
**FORMER MCCANDLESS
FUELS SITE**

2231 Delsea Drive
Franklinville, New Jersey

 10 LIPPINCOTT LA. MT. HOLLY, NJ 08060 Tel. (856) 273-1009 Fax. (856) 273-1012 1-866-Remedi-8	DESIGNED: JMM
	DETAILED: SGH
	CHECKED: JMM
SOURCE: DELTA McCandless-2	DATE: 3/13/2017
FILE NAME: 18016_DeltaSoil	JOB NO.: 18016
FIGURE: 5B	




LEGEND:

- x-x-x-x- FENCE
- ⊗ MONITORING WELL
- ⊠ TEMPORARY WELL
- SOIL BORING
- ▲ SOIL SAMPLE LOCATIONS
- (0.23) TOTAL PCBs (mg/kg)
- (ND) PCBs NOT DETECTED

PCB LEVELS:


- 100-1,000 mg/kg
- 10-100 mg/kg
- 1.0-10 mg/kg



HISTORICAL SOIL INVESTIGATION
5'-10' FEET (2008)
**FORMER MCCANDLESS
FUELS SITE**


2231 Delsea Drive
Franklinville, New Jersey

 <small>10 LIPPINCOTT LA. MT. HOLLY, NJ 08060 Tel. (856) 273-1009 Fax. (856) 273-1012 1-866-Remedi-8</small>	DESIGNED: JMM
	DETAILED: SGH
	CHECKED: JMM
SOURCE: DELTA McCandless-3	DATE: 3/13/2017
FILE NAME: 18016_DeltaSoil	JOB NO.: 18016
FIGURE: 5C	



- LEGEND:**
- x-x-x- FENCE
 - ⊗ MONITORING WELL
 - ⊠ TEMPORARY WELL
 - SOIL BORING
 - ▲ SOIL SAMPLE LOCATIONS
 - (0.23) TOTAL PCBs (mg/kg)
 - (ND) PCBs NOT DETECTED

- PCB LEVELS:**
- >1,000 mg/kg
 - 100–1,000 mg/kg
 - 10–100 mg/kg
 - 1.0–10 mg/kg



HISTORICAL SOIL INVESTIGATION
> 10 FEET (2008)
**FORMER MCCANDLESS
FUELS SITE**

2231 Delsea Drive
Franklinville, New Jersey

 <p>10 LIPPINCOTT LA. MT. HOLLY, NJ 08060 Tel. (856) 273-1009 Fax. (856) 273-1012 1-866-Remedi-8</p>	DESIGNED: JMM
	DETAILED: SGH
	CHECKED: JMM
SOURCE: DELTA McCandless-4	DATE: 3/13/2017
FILE NAME: 18016_DeltaSoil	JOB NO.: 18016
FIGURE: 5D	