

# **Community Update #94 Pompton Lakes Study Area** Pompton Lakes, New Jersey

## **Pompton Lake Dredging**

August 2018 **Community Update** 

### **EPA CLEANUP ACTIVITIES**

## **Basic Site Information—2018**

The scope of work in 2018 involves placement of the eco-layer in the Island Area and the ABD as well as site restoration. Hydraulic dredging, processing and off-site disposal of sediment containing mainly mercury and lead in a 36-acre area within Pompton Lake called the Acid Brook Delta (ABD) is complete. The work will be performed by The Chemours Company FC, LLC., through its contractor, Sevenson Environmental Services with EPA/ NJDEP oversight.

## **Further information/contacts:**

## **Borough of Pompton Lakes** http://www.pomptonlakesgov.com

#### **EPA Remedial Project Manager**

Perry Katz (212) 637-4426 katz.ira-perry@epa.gov

## **EPA Community Involvement** Coordinator

Pat Seppi (646) 369-0068 seppi.pat@epa.gov EPA's 94th update is to inform the community of the progress of activities related to the dredging performed on the 36-acre portion of the Pompton Lake Study Area known as the Acid Brook Delta (ABD).

## **Activities performed (week of August 13th):**

- Continued restoration work associated with Island Area, Uplands Soil Areas, ABD shoreline and Acid Brook.
- Continued demobilization of equipment no longer needed on-site.
- Lake turbidity/ perimeter air (dust) monitoring is complete as water work is complete and there is no impacted material on-site.
- Monitoring data posted at www.pomptonlakesworks.com/pompton-lakeproject/environmental-monitoring

## Activities scheduled (week of August 20th):

- Continue activities on-site for restoration of Upland Soil Areas, ABD shoreline, and Acid Brook.
- Continue demobilization equipment.
- Continue routine inspection of site work areas per approved permits and for safety purposes.

#### **Notes:**

WORK ON SATURDAY, AUGUST 18TH (8 A.M. TILL 5 P.M.) IN-VOLVED WATERING OF PLANTS, AS NEEDED. GATES WILL BE CLOSED TO THE EXTENT PRACTICABLE.

PHOTOS: THE FIRST PHOTO IS THE BIKE RACK INSTALLED IN LAKESIDE PARK. THE SECOND PHOTO SHOWS THE IN-STALLATION OF THE CONCRETE WALKWAY IN ROTARY PARK.

EPA CONTINUES ITS PRESENCE AT BOROUGH HALL THURS-DAYS FROM 10A.M. TILL 4P.M.