

United States Environmental Protection Agency



ANNUAL CLASS II DISPOSAL/INJECTION WELL MONITORING REPORT

Name, Address, Phone and/or Email of Permittee

Benson Energy, LLC of PA
772 Champlin Hill Rd.
Smethport, PA 16749

State

Pennsylvania

County

McKean

WELL TYPE

- Brine Disposal
- Enhanced Recovery
- Hydrocarbon Storage

Locate well in two directions from nearest lines of quarter section and drilling unit

Surface Location

1/4 of 1/4 of Section Township Range

ft. from (N/S) Line of quarter section

ft. from (E/W) Line of quarter section.

✓ See attached well location plat

Latitude

Longitude

Permit or EPA ID Number

PA52R903BMCK

API Number

37-083-55287-00

Full Well Name

Benson 6

INJECTION PRESSURE

TOTAL VOLUME INJECTED

TUBING - CASING ANNULUS PRESSURE (IF SPECIFIED IN PERMIT)

MONTH, YEAR	MAXIMUM PSIG	BBL	MCF	MAXIMUM PSIG
Jan	—	—		
Feb	285	80		
March	310	145		
April		120		
May		150		
June	360	102		
July	300	81		
August	385	150		
September	305	60		
September Oct	375	131		
November	365	110		
December	385	140		

Certification

I certify under the penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment. (Ref. 40 CFR § 144.32)

Name and Official Title (Please type or print)

Brice N. Benson - President

Signature

Date Signed

1-18-2022