




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

1.	Date Taken: 04/04/2024	Time Taken: 10:02 AM ET
	Sample No.: IMG_0590	
	Description of Digital Image: Test photo of EPA inspection photo log ensuring date and time were accurate.	
	Modifications: Reduced scale of photo for the purpose of inspection report.	





File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

2.	Date Taken: 04/04/2024	Time Taken: 10:04 AM ET	
	Sample No.: IMG_0591		
	Description of Digital Image: Main Level – Gymnasium: SAW gymnasium and gym risers viewed from the stage.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

3.	Date Taken: 04/04/2024	Time Taken: 10:05 AM ET	
	Sample No.: IMG_0592		
	Description of Digital Image: Main Level – Gymnasium: New heater lines, stage left (south).		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

4.	Date Taken: 04/04/2024	Time Taken: 10:05 AM ET	
	Sample No.: IMG_0593		
	Description of Digital Image: Main Level – Gymnasium: New heater lines stage right (North). O&M activities observed on large pipe TSI at the bottom left of photo.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

5.	Date Taken: 04/04/2024	Time Taken: 10:06 AM ET	
	Sample No.: IMG_0594		
	Description of Digital Image: Main Level – Gymnasium: Stage right northern stairwell crumbling ceiling plaster, flaking paint, broken and loose floor tile.		
Modifications: Reduced scale of photo for the purpose of inspection report.			


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

6.	Date Taken: 04/04/2024	Time Taken: 10:09 AM ET	
	Sample No.: IMG_0595		
	Description of Digital Image: Main Level – Gymnasium: Stage left southern stairwell crumbling ceiling and wall plaster with flaking paint.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

7.	Date Taken: 04/04/2024	Time Taken: 10:14 AM ET	
	Sample No.: IMG_0596		
	Description of Digital Image: Main Level – Gymnasium: Southeastern storage closet, crumbling ceiling and wall painted plaster with new and old piping, debris covered floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

8.	Date Taken: 04/04/2024	Time Taken: 10:14 AM ET	
	Sample No.: IMG_0597		
	Description of Digital Image: Main Level – Gymnasium: Southeastern storage closet, crumbling ceiling and wall painted plaster with new and old piping, debris covered floor. Close up of ceiling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


9.	Date Taken: 04/04/2024	Time Taken: 10:14 AM ET	
	Sample No.: IMG_0598		
	Description of Digital Image: Main Level – Gymnasium: Southeastern storage closet, crumbling ceiling and wall painted plaster with new and old piping, debris covered floor. Close up of condition of floor.		
Modifications: Reduced scale of photo for the purpose of inspection report.			



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

10.	Date Taken: 04/04/2024	Time Taken: 10:15 AM ET	
	Sample No.: IMG_0599		
	Description of Digital Image: Main Level – Gymnasium: Mixed ceiling tiles above gym risers, many damaged, missing and paint flaking from wall.		
Modifications: Reduced scale of photo for the purpose of inspection report.			

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

11.	Date Taken: 04/04/2024	Time Taken: 10:19 AM ET	 <p style="text-align: right; color: orange;">04/04/2024 10:19</p>
	Sample No.: IMG_0600		
	Description of Digital Image: Main Level – Northwest gym closet/storage room severely damaged building materials and ceiling collapsing into the room with debris covering the floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

12.	Date Taken: 04/04/2024	Time Taken: 10:20 AM ET	
	Sample No.: IMG_0601		
	Description of Digital Image: Main Level – Northwest gym closet/storage room close-up of the ceiling and building material debris covering the floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

13.	Date Taken: 04/04/2024	Time Taken: 10:20 AM ET	
	Sample No.: IMG_0602		
	Description of Digital Image: Main Level – Northwest gym closet/storage room close-up of ceiling damage.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

14.	Date Taken: 04/04/2024	Time Taken: 10:20 AM ET	
	Sample No.: IMG_0603		
	Description of Digital Image: Main Level – Northwest gym closet/storage room ceiling and building material debris covering the room and stored school supplies.		
Modifications: Reduced scale of photo for the purpose of inspection report.			

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

15.	Date Taken: 04/04/2024	Time Taken: 10:25 AM ET	
	Sample No.: IMG_0604		
	Description of Digital Image: Main Level – Southwest Storage room/kitchen scraped paint debris/flakes in yellow mop bucket.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


16.	Date Taken: 04/04/2024	Time Taken: 10:25 AM ET	
	Sample No.: IMG_0605		
	Description of Digital Image: Main Level – Southwest Storage room/kitchen painting supplies in trash can.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

17.	Date Taken: 04/04/2024	Time Taken: 10:25 AM ET	
	Sample No.: IMG_0606		
	Description of Digital Image: Main Level – Southwest Storage room/kitchen paint and cleaning supplies.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

18.	Date Taken: 04/04/2024	Time Taken: 10:26 AM ET	
	Sample No.: IMG_0607		
	Description of Digital Image: Main Level – Southwest Storage room/kitchen ceiling leak, glue, and paint damage.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

19.	Date Taken: 04/04/2024	Time Taken: 10:25 AM ET	
	Sample No.: IMG_0608		
	Description of Digital Image: Main Level – Southwest Storage room/kitchen ceiling leak, glue, and paint damage.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

20.	Date Taken: 04/04/2024	Time Taken: 10:30 AM ET	 <p>A photograph of a storage room with several tall metal lockers. The ceiling shows significant damage, including a large hole and peeling paint. A black trash bin with a cardboard box on top and a yellow bin are in the foreground. A timestamp '04/04/2024 10:30' is visible in the bottom right corner of the photo.</p>
	Sample No.: IMG_0609		
	Description of Digital Image: Main Level – Southwest Storage room/kitchen ceiling leak, glue, and paint damage full room photo.		
Modifications: Reduced scale of photo for the purpose of inspection report.			


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

21.	Date Taken: 04/04/2024	Time Taken: 10:30 AM ET	
	Sample No.: IMG_0610		
	Description of Digital Image: Lower Level – Southwest Stairway to Lower-Level Water meter room: Pipe runs running through the wall into the water meter room with visible debris covering the floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

22.	Date Taken: 04/04/2024	Time Taken: 10:31 AM ET	 <p style="text-align: right; color: orange;">04/04/2024 10:31</p>
	Sample No.: IMG_0611		
	Description of Digital Image: Lower Level – Southwest Stairway to Lower-Level Water meter room: ceiling plaster/paint debris covering the floor.		
Modifications: Reduced scale of photo for the purpose of inspection report.			

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


23.	Date Taken: 04/04/2024	Time Taken: 10:35 AM ET	
	Sample No.: IMG_0612		
	Description of Digital Image: Lower Level – Custodial Closet/Abandoned Bathroom: View of the ceiling at the entrance of the custodial closet. Significantly damaged flaking painted ceiling material and possible asbestos containing thermal system insulation (TSI) aerosol was observed		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

24.	Date Taken: 04/04/2024	Time Taken: 10:35 AM ET	 <p style="text-align: right; color: orange;">04/04/2024 10:35</p>
	Sample No.: IMG_0613		
	Description of Digital Image: Lower Level – Custodial Closet/Abandoned Bathroom: significantly damaged plaster and other ceiling materials that fell, covered the floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

25.	Date Taken: 04/04/2024	Time Taken: 10:36 AM ET	
	Sample No.: IMG_0614		
	Description of Digital Image: Lower Level – Custodial Closet/Abandoned Bathroom: ceiling debris covering the floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

26.	Date Taken: 04/04/2024	Time Taken: 10:36 AM ET	
	Sample No.: IMG_0615		
	Description of Digital Image: Lower Level – Custodial Closet/Abandoned Bathroom: ceiling debris covering the floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


27.	Date Taken: 04/04/2024	Time Taken: 10:39 AM ET	
	Sample No.: IMG_0616		
	Description of Digital Image: Lower Level – Cafeteria: The cafeteria contained blue 9”x9” floor tile in fair condition. The cafeteria’s 2’x4’ ceiling tile appeared to be new and a 4” horizontal line with minor damage spanned the southern wall hung from the ceiling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

28.	Date Taken: 04/04/2024	Time Taken: 10:42 AM ET	
	Sample No.: IMG_0617		
	Description of Digital Image: Lower Level – Boiler room: Full frame photo of boiler room. In the first room, two cracked/damaged boiler gaskets from the old boilers are laid on the cart table in the center and against the brick wall in the bottom left of the photo.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


29.	Date Taken: 04/04/2024	Time Taken: 10:43 AM ET	
	Sample No.: IMG_0618		
	Description of Digital Image: Lower Level – Boiler room: Close up photo of a removed broken up boiler gasket on roller cart.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

30.	Date Taken: 04/04/2024	Time Taken: 10:43 AM ET	
	Sample No.: IMG_0619		
	Description of Digital Image: Lower Level – Boiler room: Close up photo of a removed broken up boiler gasket on roller cart.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

31.	Date Taken: 04/04/2024	Time Taken: 10:44 AM ET	
	Sample No.: IMG_0620		
	Description of Digital Image: Lower Level – Boiler room: Close up photo of a removed damaged gasket stored against the brick wall.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

32.	Date Taken: 04/04/2024	Time Taken: 10:44 AM ET	
	Sample No.: IMG_0621		
	Description of Digital Image: Lower Level – Boiler room: Side profile close up photo of a removed broken up boiler gasket stored against the brick wall.		
Modifications: Reduced scale of photo for the purpose of inspection report.			



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


33.	Date Taken: 04/04/2024	Time Taken: 10:46 AM ET	
	Sample No.: IMG_0622		
	Description of Digital Image: Lower Level – Boiler room: Main room with the old boilers (right and left) and new boiler at the center.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

34.	Date Taken: 04/04/2024	Time Taken: 10:46 AM ET	
	Sample No.: IMG_0623		
	Description of Digital Image: Lower Level – Boiler room: Main room close up photo of the old boiler (right) where the gasket was removed.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

35.	Date Taken: 04/04/2024	Time Taken: 10:47 AM ET	
	Sample No.: IMG_0624		
	Description of Digital Image: Lower Level – Boiler room: Damaged TSI throughout the boiler room.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

36.	Date Taken: 04/04/2024	Time Taken: 10:48 AM ET	
	Sample No.: IMG_0625		
	Description of Digital Image: Lower Level – Boiler room: Damaged TSI throughout the boiler room.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


37.	Date Taken: 04/04/2024	Time Taken: 10:52 AM ET	
	Sample No.: IMG_626		
	Description of Digital Image: Lower Level - Map		
	Modifications: Reduced scale of photo for the purpose of inspection report.		




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

38.	Date Taken: 04/04/2024	Time Taken: 10:54 AM ET	
	Sample No.: IMG_0627		
	Description of Digital Image: Lower Level – Hallway with terrazzo flooring and 2x4' drop ceiling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

39.	Date Taken: 04/04/2024	Time Taken: 10:56 AM ET	
	Sample No.: IMG_0628		
	Description of Digital Image: Lower Level – Instruction area/Book supplies storage/ Crystal Clear Staff area: Full room photo with the instruction area on the left and staff area on the right. The whole area had removed floor tile with exposed black mastic.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

40.	Date Taken: 04/04/2024	Time Taken: 10:57 AM ET	
	Sample No.: IMG_0629		
	Description of Digital Image: Lower Level – Instruction area/Book supplies storage/ Crystal Clear Staff area: Book supply storage and instruction area set up with pipe TSI along the wall and black flooring mastic.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

41.	Date Taken: 04/04/2024	Time Taken: 10:57 AM ET	
	Sample No.: IMG_0630		
	Description of Digital Image: Lower Level – Instruction area/Book supplies storage/ Crystal Clear Staff area: Make shift waste bin with yellow and blue streamer on top of discarded ceiling tile.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

42.	Date Taken: 04/04/2024	Time Taken: 10:57 AM ET	
	Sample No.: IMG_0631		
	Description of Digital Image: Lower Level – Instruction area/Book supplies storage/ Crystal Clear Staff area: Ceiling of Crystal Clear staff area, with damaged and mismatched ceiling tiles along with exposed glue puck. Pipe TSI runs the perimeter of the room.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


43.	Date Taken: 04/04/2024	Time Taken: 10:57 AM ET	
	Sample No.: IMG_0632		
	Description of Digital Image: Lower Level – Instruction area/Book supplies storage/ Crystal Clear Staff area: Crystal Clear staff area full area photo.		
Modifications: Reduced scale of photo for the purpose of inspection report.			




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

44.	Date Taken: 04/04/2024	Time Taken: 11:02 AM ET	
	Sample No.: IMG_0633		
	Description of Digital Image: Lower Level – Instruction area/Book supplies storage/ Crystal Clear Staff area: Rear portion of Crystal-Clear staff area. The pipe TSI extends the perimeter of the room past the school supplies stored at the back of the room.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

45.	Date Taken: 04/04/2024	Time Taken: 11:03 AM ET	
	Sample No.: IMG_0634		
	Description of Digital Image: Lower Level – Instruction area/Book supplies storage/ Crystal Clear Staff area: Close up of ceiling tiles and exposed glue pucks above Crystal Clear staff area.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

46.	Date Taken: 04/04/2024	Time Taken: 11:05 AM ET	
	Sample No.: IMG_0635		
	Description of Digital Image: Main Level – Floor plan Map		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

47.	Date Taken: 04/04/2024	Time Taken: 11:06 AM ET	 <p>A photograph of Classroom 109, a main level classroom. The room features a blue accent wall, a whiteboard with colorful charts, and several wooden tables with black chairs. A timestamp '04/04/2024 11:06' is visible in the bottom right corner of the photo.</p>
	Sample No.: IMG_0636		
	Description of Digital Image: Main Level – Classroom 109: Equipped with 2x4’ acoustical drop ceiling and 12”x 12” tan floor tile		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

48.	Date Taken: 04/04/2024	Time Taken: 11:08 AM ET	
	Sample No.: IMG_0637		
	Description of Digital Image: Main Level – Classroom 107: Cove Base/Base board and adhesive were observed to be peeling away from the wall at the southwestern section of the classroom near childrens play sets.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

49.	Date Taken: 04/04/2024	Time Taken: 11:11 AM ET	
	Sample No.: IMG_0638		
	Description of Digital Image: Main Level – Hallway: Two types of floor surfacing throughout the hallway. The first nearest the photographer is tile and the second beyond the hallway divider is terrazzo with 2x4' drop ceiling tiles throughout.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

50.	Date Taken: 04/04/2024	Time Taken: 11:14 AM ET	
	Sample No.: IMG_0639		
	Description of Digital Image: Second Level – Hallway: Terrazzo flooring and plaster ceiling and walls.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


51.	Date Taken: 04/04/2024	Time Taken: 11:16 AM ET	
	Sample No.: IMG_0640		
	Description of Digital Image: Second Level – Technology and Server Room: Terrazzo flooring with chipping and flaking painted wall materials, debris covered the floor.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


52.	Date Taken: 04/04/2024	Time Taken: 11:17 AM ET	 <p>04/04/2024 11:17</p>
	Sample No.: IMG_0641		
	Description of Digital Image: Second Level – Technology and Server Room: Close up of wall materials and paint debris covering the ground.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


53.	Date Taken: 04/04/2024	Time Taken: 11:19 AM ET	
	Sample No.: IMG_0642		
	Description of Digital Image: Second Level – Floor plan diagram map.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


54.	Date Taken: 04/04/2024	Time Taken: 11:21 AM ET	
	Sample No.: IMG_0643		
	Description of Digital Image: Second Level – Women’s Restroom: A pipe run of aerosol TSI spanned the width of the restroom above the window with duct tape patches observed on the pipe elbow in fair/damaged condition.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

55.	Date Taken: 04/04/2024	Time Taken: 11:21 AM ET	
	Sample No.: IMG_0644		
	Description of Digital Image: Second Level – Women’s Restroom: Close up of the pipe run of aerosol TSI that spanned the width of the restroom above the window with duct tape patches observed on the pipe elbow in fair/damaged condition.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

56.	Date Taken: 04/04/2024	Time Taken: 11:24 AM ET	
	Sample No.: IMG_0645		
	Description of Digital Image: Third Level – Southwestern Custodial Closet: The closet contained stacked/piled classroom desks and chairs. The ceiling was observed to be severely flaking and damaged.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

57.	Date Taken: 04/04/2024	Time Taken: 11:24 AM ET	
	Sample No.: IMG_0646		
	Description of Digital Image: Third Level – Southwestern Custodial Closet: The closet contained a sink bowl filled with a pulverized/dust- like powder material.		
Modifications: Reduced scale of photo for the purpose of inspection report.			

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

58.	Date Taken: 04/04/2024	Time Taken: 11:26 AM ET	
	Sample No.: IMG_0647		
	Description of Digital Image: Third Level – Hallway: Similar to the Second & first level Hallways, the floor was observed to be tile that transitioned to terrazzo beyond the hallway divider with a plaster ceiling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

59.	Date Taken: 04/04/2024	Time Taken: 11:28 AM ET	
	Sample No.: IMG_0648		
	Description of Digital Image: Third Level – Classroom 302/old Lab room: The wall and ceiling materials were painted plaster in a damaged and flaking condition. Dust and Debris covered flat surfaces and the floor. The room had old lab tables commonly known to be asbestos containing as well as a fire blanket stored at the front of the room against the blackboard.		
Modifications: Reduced scale of photo for the purpose of inspection report.			

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

60.	Date Taken: 04/04/2024	Time Taken: 11:29 AM ET	
	Sample No.: IMG_0649		
	Description of Digital Image: Third Level – Classroom 302/old Lab room: Close up of the black lab tables and layer of dust/debris.		
Modifications: Reduced scale of photo for the purpose of inspection report.			



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


61.	Date Taken: 04/04/2024	Time Taken: 11:29 AM ET	
	Sample No.: IMG_0650		
	Description of Digital Image: Third Level – Classroom 302/old Lab room: Photo of the crumbling plaster ceiling and damaged condition of the wall materials.		
Modifications: Reduced scale of photo for the purpose of inspection report.			




File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

62.	Date Taken: 04/04/2024	Time Taken: 11:29 AM ET	
	Sample No.: IMG_0651		
	Description of Digital Image: Third Level – Classroom 302/old Lab room: Close-up of deteriorated wall materials and layer of dust/debris on flooring.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


63.	Date Taken: 04/04/2024	Time Taken: 11:30 AM ET	
	Sample No.: IMG_0652		
	Description of Digital Image: Third Level – Classroom 302/old Lab room: Close-up of the damaged ceiling plaster in image 0650.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


64.	Date Taken: 04/04/2024	Time Taken: 11:30 AM ET	
	Sample No.: IMG_0653		
	Description of Digital Image: Third Level – Classroom 302/old Lab room: Close up of the fire blanket and blackboard.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

65.	Date Taken: 04/04/2024	Time Taken: 11:35 AM ET	
	Sample No.: IMG_0654		
	Description of Digital Image: Third Level – Classroom 301/Library: The painted materials of the wall in the classroom were observed to be flaking and peeling off in large sections in areas bordering the windows and on the ceiling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

66.	Date Taken: 04/04/2024	Time Taken: 11:37 AM ET	 <p>04/04/2024 11:37</p>
	Sample No.: IMG_0655		
	Description of Digital Image: Third Level – Classroom 306: The painted materials of the wall in the classroom were observed to be flaking and peeling off in large sections in areas bordering the windows and crumbling from the ceiling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

67.	Date Taken: 04/04/2024	Time Taken: 11:37 AM ET	
	Sample No.: IMG_0656		
	Description of Digital Image: Third Level – Classroom 306: The painted materials of the wall in the classroom were observed to be flaking and peeling off in large sections in areas bordering the windows and crumbling from the ceiling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		


File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

68.	Date Taken: 04/04/2024	Time Taken: 11:39 AM ET	
	Sample No.: IMG_0657		
	Description of Digital Image: Third Level – East End Men’s Restroom: Painted ceiling significantly peeling.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

69	Date Taken: 04/04/2024	Time Taken: 11:40 AM ET	
	Sample No.: IMG_0658		
	Description of Digital Image: Third Level – East End Women’s/Staff Restroom: The ceiling had significant damage with cracks and holes in the plaster around piping.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


70.	Date Taken: 04/04/2024	Time Taken: 11:43 AM ET	
	Sample No.: IMG_0659		
	Description of Digital Image: Third Level – Classroom 309: Ceiling plaster observed to be significantly damaged with a large chunk dangling from the ceiling. Additionally, the wall materials showed significant cracking, peeling, and flaking. The Cove base/baseboard around the perimeter of the room were peeling away from the wall leaving the adhesive exposed. At the entrance to the classroom a gap existed between the carpet and hallway floor tile leaving exposed black mastic.		
	Modifications:		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

	Reduced scale of photo for the purpose of inspection report.	
--	--	--

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

71.	Date Taken: 04/04/2024	Time Taken: 11:43 AM ET	
	Sample No.: IMG_0660		
	Description of Digital Image: Third Level – Classroom 309: Close up of the wall materials showed significant cracking, peeling, and flaking.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:


72.	Date Taken: 04/04/2024	Time Taken: 11:43 AM ET	
	Sample No.: IMG_0661		
	Description of Digital Image: Third Level – Classroom 309: Close up of the wall materials showed significant cracking, peeling, and flaking.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		

File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

73.	Date Taken: 04/04/2024	Time Taken: 11:44 AM ET	
	Sample No.: IMG_0662		
	Description of Digital Image: Third Level – Classroom 309: Close-up of the Cove base/baseboard around the perimeter of the room were peeling away from the wall leaving the adhesive exposed.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

74.	Date Taken: 04/04/2024	Time Taken: 11:45 AM ET	
	Sample No.: IMG_0663		
	Description of Digital Image: Third Level – Classroom 309: Close-up of the entrance to the classroom a gap existed between the carpet and hallway floor tile leaving exposed black mastic.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		



File Number: 24TA007	Entity Name: ACCEL Schools – Steam Academy of Warren	Inspection Address, City, State, Zip Code: 261 Elm Road Northeast, Warren, Ohio 44483
Date of Inspection: April 4, 2024	Inspector-Photographer: Brandon Brewster	Number of Photographs Taken: 75
Camera Used: SY2376	Digital Recording Media: SD CARD	Notes:

75.	Date Taken: 04/04/2024	Time Taken: 12:05 AM ET	
	Sample No.: IMG_0664		
	Description of Digital Image: Photo of the exterior rear parking lot of the Steam Academy of Warren School building.		
	Modifications: Reduced scale of photo for the purpose of inspection report.		